

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
Cedar Building - Room C4 Southwest Corner	Sink	7/13/2016	ECES-I-001	9.17											
Cedar Building - Hallway West Side	Fountain	7/13/2016	ECES-I-002	6.66											
Cedar Building - Room C3 Northwest Corner	Sink	7/13/2016	ECES-I-003	6.34											
Cedar Building - Hallway East Side	Fountain	7/13/2016	ECES-I-004	3.23											
Cedar Building - Boys Restroom West Wall	Sink	7/13/2016	ECES-I-005	4.59											
Cedar Building - Girls Restroom East Wall	Sink	7/13/2016	ECES-I-006	4.19											
Cedar Building - Room C2 Northeast Corner	Sink	7/13/2016	ECES-I-007	9.59											
Cedar Building - Room C1 Southeast Corner	Sink	7/13/2016	ECES-I-008	4.39											
Birch Building - Room B4 - Southwest Corner	Sink	7/13/2016	ECES-I-009	3.28											
Birch Building - Hallway East Wall	Fountain	7/13/2016	ECES-I-010	9.69											
Birch Building - Room B3 Northwest Corner	Sink	7/13/2016	ECES-I-011	0.44											
Birch Building - Boys Restroom West Wall	Sink	7/13/2016	ECES-I-012	5.80											
Birch Building - Girls Restroom East Wall	Sink	7/13/2016	ECES-I-013	2.43											
Birch Building - Room B2 Northeast Corner	Sink	7/13/2016	ECES-I-014	7.26											
Birch Building - Hallway West Wall	Fountain	7/13/2016	ECES-I-015	6.46											
Birch Building - Room B1 Southeast Corner	Sink	7/13/2016	ECES-I-016	6.99											
Alder Building - Room A4 Southwest Corner	Sink	7/13/2016	ECES-I-017	4.68											
Alder Building - Hallway East Wall	Fountain	7/13/2016	ECES-I-018	18.80											
Alder Building - Boys Restroom West Wall	Sink	7/13/2016	ECES-I-019	2.81											
Alder Building - Girls Restroom East Wall	Sink	7/13/2016	ECES-I-020	8.23											
Alder Building - Room A3 Northwest Corner	Sink	7/13/2016	ECES-I-021	3.62											
Alder Building - Room A2 Northeast Corner	Sink	7/13/2016	ECES-I-022	2.92											
Alder Building - Room A1 Southeast Corner	Sink	7/13/2016	ECES-I-023	5.84											
Alder Building - Hallway West Wall	Fountain	7/13/2016	ECES-I-024	14.80											
Main Office - Production Room North/Center Wall	Sink	7/13/2016	ECES-I-025	41.90	9/2/2016	ECES-F-061	3.29	9/9/2016	9/12/2016	ECES-I-072	28.70	Replace Angle Stops and Nipples	11/18/2016	ECES-I-076	3.32
Main Office - Outside Staff Resource Room	Fountain	7/13/2016	ECES-I-026	2.50											
Main Office - South Side Women's Restroom West Wall	Sink	7/13/2016	ECES-I-027	10.40											
Main Office - South Side Unisex Restroom East Wall	Sink	7/13/2016	ECES-I-028	7.50											
Main Office - South Side Staff Lunchroom East Wall	Insta-Hot	7/13/2016	ECES-I-029	2.72											
Main Office - South Side Staff Lunchroom East Wall	Sink	7/13/2016	ECES-I-030	7.92											
Main Office - Mail/Office Supply Room South Wall	Sink	7/13/2016	ECES-I-031	58.90	9/2/2016	ECES-F-060	ND	9/9/2016	9/12/2016	ECES-I-071	11.90				
Main Office - Health Room Northeast Corner	Sink	7/13/2016	ECES-I-032	11.10											
Main Office - North Side Health room Emergency Restroom	Sink	7/13/2016	ECES-I-033	26.90	9/2/2016	ECES-F-063	2.67	9/9/2016	9/12/2016	ECES-I-070	10.20				
Main Office - Instructional Materials Room	Sink	7/13/2016	ECES-I-034	67.20	9/2/2016	ECES-F-062	ND	9/9/2016	9/12/2016	ECES-I-073	23.40	Replace Angle Stops and Nipples	11/18/2016	ECES-I-077	1.93
Main Office - North Hallway Outside Inst Mat Room	Fountain	7/13/2016	ECES-I-035	4.11											
Douglas Fir Building - Room D1 Southwest Corner	Sink	7/13/2016	ECES-I-036	7.52											
Douglas Fir Building - Room D1 Southwest Corner	Fountain	7/13/2016	ECES-I-037	1.86											
Douglas Fir Building - Room D2 Northwest Corner	Sink	7/13/2016	ECES-I-038	31.20	9/2/2016	ECES-F-067	3.15	9/9/2016	9/12/2016	ECES-I-075	2.57				
Douglas Fir Building - Room D2 Northwest Corner	Fountain	7/13/2016	ECES-I-039	0.72											
Douglas Fir Building - Boys Restroom East Wall	Sink	7/13/2016	ECES-I-040	1.90											
Douglas Fir Building - Girls Restroom West Wall	Sink	7/13/2016	ECES-I-041	0.70											
Douglas Fir Building - Room D3 Northeast Corner	Sink	7/13/2016	ECES-I-042	7.64											
Douglas Fir Building - Room D3 Northeast Corner	Fountain	7/13/2016	ECES-I-043	3.10											
Douglas Fir Building - Room D4 Southeast Corner	Sink	7/13/2016	ECES-I-044	16.80											
Douglas Fir Building - Room D4 Southeast Corner	Fountain	7/13/2016	ECES-I-045	3.21											
Evergreen Building - Room E1 Southwest Corner	Sink	7/13/2016	ECES-I-046	3.50											
Evergreen Building - Room E1 Southwest Corner	Fountain	7/13/2016	ECES-I-047	4.59											
Evergreen Building - Room E2 Northwest Corner	Sink	7/13/2016	ECES-I-048	3.58											
Evergreen Building - Room E2 Northwest Corner	Fountain	7/13/2016	ECES-I-049	4.29											
Evergreen Building - Girls Restroom West Wall	Sink	7/13/2016	ECES-I-050	4.46											
Evergreen Building - Boys Restroom East Wall	Sink	7/13/2016	ECES-I-051	2.90											
Evergreen Building - Room E3 Northeast Corner	Sink	7/13/2016	ECES-I-052	26.70	9/2/2016	ECES-F-064	ND	9/9/2016	9/12/2016	ECES-I-074	2.22				
Evergreen Building - Room E3 Northeast Corner	Fountain	7/13/2016	ECES-I-053	1.66											
Evergreen Building - Cafeteria East Wall	Sink	7/13/2016	ECES-I-054	1.58											
Evergreen Building - Cafeteria South Wall	Sink	7/13/2016	ECES-I-055	6.49											
Evergreen Building - Cafeteria Restroom Southwest Corner	Sink	7/13/2016	ECES-I-056	20.00											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw				
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)	
Edgewood Community Elementary School																
Boys Restroom - West Wall Outside Gym	Sink	7/13/2016	ECES-I-057	3.77												
Girls Restroom - East Wall Outside Gym	Sink	7/13/2016	ECES-I-058	4.01												
Drinking Fountain Outside Restrooms - Outside Gym	Fountain	7/13/2016	ECES-I-059	0.97												
Classroom 105 West Wall	Fountain	9/2/2016	ECES-I-068	ND												
Classroom 105 West Wall	Sink	9/2/2016	ECES-I-069	2.79												
Evergreen Building - Room E4	Fountain	9/2/2016	ECES-I-065	1.72												
Evergreen Building - Room E4	Sink	9/2/2016	ECES-I-066	2.15												
Fixture Types: DF= Drinking Fountain S= Sink IH= Instahot FR= Fridge HB= Hose Bib																
Total Samples Taken	77.00	Total Elevated on 1st Draw		63.00	Total Elevated on Flush Draw		6.00	Total Elevated on Final/Replacement Draw				6.00				2.00

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.