

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Arts & Technology Academy											
Room 10	Sink	7/8/2016	ATAMS-I-001	8.23							
Room 4	Fountain	7/8/2016	ATAMS-I-002	2.30							
Room 9 Northwest Corner (East)	Sink	7/8/2016	ATAMS-I-003	10.30							
Room 9 Northwest Corner	Fountain	7/8/2016	ATAMS-I-004	5.83							
Room 9 Northwest Corner (West)	Sink	7/8/2016	ATAMS-I-005	20.80	9/8/2016	ATAMS-F-062	1.90	Decommissioned	Decommissioned.	Decommissioned.	Decommissioned.
Cafeteria Wing Boys Restroom	Sink	7/8/2016	ATAMS-I-006	4.67							
Cafeteria Wing Girls Restroom	Sink	7/8/2016	ATAMS-I-007	4.43							
Room 6	Fountain	7/8/2016	ATAMS-I-008	2.37							
Room 6	Sink	7/8/2016	ATAMS-I-009	2.85							
Kitchen Dishwashing Room	Sink	7/8/2016	ATAMS-I-010	5.46							
Kitchen Women's Restroom	Sink	7/8/2016	ATAMS-I-011	3.22							
Kitchen Handwash	Sink	7/8/2016	ATAMS-I-012	3.53							
Kitchen Prep Sink	Sink	7/8/2016	ATAMS-I-013	3.11							
Cafeteria	Fountain	7/8/2016	ATAMS-I-014	1.07							
Cafeteria Wing Corridor (Triple Sink)	Sink	7/8/2016	ATAMS-I-015	2.04							
Cafeteria Wing Corridor (Single Sink)	Sink	7/8/2016	ATAMS-I-016	2.19							
Cafeteria Wing Corridor	Fountain	7/8/2016	ATAMS-I-017	1.81							
Staff Lounge	Insta-Hot	7/8/2016	ATAMS-I-018	0.76							
Staff Lounge	Sink	7/8/2016	ATAMS-I-019	1.56							
Office Area Staff Men's Restroom	Sink	7/8/2016	ATAMS-I-020	1.24							
Office Area Staff Women's Restroom	Sink	7/8/2016	ATAMS-I-021	6.51							
Office Area Staff Unisex Restroom	Sink	7/8/2016	ATAMS-I-022	4.41							
Health Room	Sink	7/8/2016	ATAMS-I-023	6.64							
Northwest Wing Boys Restroom	Sink	7/8/2016	ATAMS-I-024	1.79							
Northwest Wing Corridor	Sink	7/8/2016	ATAMS-I-025	7.51							
Northwest Wing Girls Restroom	Sink	7/8/2016	ATAMS-I-026	3.22							
Room 13 Double Sink	Fountain	7/8/2016	ATAMS-I-027	11.20							
Room 13 Double Sink	Sink	7/8/2016	ATAMS-I-028	10.80							
Room 13 Single Sink	Sink	7/8/2016	ATAMS-I-029	17.20							
Room 15	Fountain	7/8/2016	ATAMS-I-030	1.36							
Room 15	Sink	7/8/2016	ATAMS-I-031	3.31							
Room 16	Sink	7/8/2016	ATAMS-I-032	26.90	9/8/2016	ATAMS-F-063	2.25	Decommissioned.	Decommissioned.	Decommissioned.	Decommissioned.
Room 16	Fountain	7/8/2016	ATAMS-I-033	7.60							
Northwest Wing Corridor (Center)	Fountain	7/8/2016	ATAMS-I-034	3.40							
Northwest Wing Storage Room (North)	Sink	7/8/2016	ATAMS-I-035	9.20							
Northwest Wing Storage Room (South)	Sink	7/8/2016	ATAMS-I-036	25.50	9/8/2016	ATAMS-F-064	1.98	Decommissioned.	Decommissioned.	Decommissioned.	Decommissioned.
Room 17	Sink	7/8/2016	ATAMS-I-037	2.23							
Room 17	Fountain	7/8/2016	ATAMS-I-038	1.34							
Room 18	Sink	7/8/2016	ATAMS-I-039	3.90							
Room 18	Fountain	7/8/2016	ATAMS-I-040	0.83							
Room 19	Sink	7/8/2016	ATAMS-I-041	2.76							
Room 19	Fountain	7/8/2016	ATAMS-I-042	1.39							
Library	Sink	7/8/2016	ATAMS-I-043	7.67							
Room 28	Sink	7/8/2016	ATAMS-I-044	2.78							
Room 28	Fountain	7/8/2016	ATAMS-I-045	0.41							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Arts & Technology Academy											
Room 27 North Wall (West)	Sink	7/8/2016	ATAMS-I-046	1.60							
Room 27 North Wall (East)	Sink	7/8/2016	ATAMS-I-047	4.82							
Room 27 East Wall	Sink	7/8/2016	ATAMS-I-048	2.39							
Room 27 East Wall	Fountain	7/8/2016	ATAMS-I-049	0.50							
Room 26	Sink	7/8/2016	ATAMS-I-050	2.69							
Room 26	Fountain	7/8/2016	ATAMS-I-051	1.81							
West Wing Corridor (Center)	Fountain	7/8/2016	ATAMS-I-052	21.10	9/8/2016	ATAMS-F-065	1.13	Decommissioned.	Decommissioned.	Decommissioned.	Decommissioned.
Room 22	Sink	7/8/2016	ATAMS-I-053	1.27							
Room 22	Fountain	7/8/2016	ATAMS-I-054	0.43							
West Wing Girls Restroom	Sink	7/8/2016	ATAMS-I-055	14.90							
West Wing Boys Restroom	Sink	7/8/2016	ATAMS-I-056	16.10							
West Wing East End	Fountain	7/8/2016	ATAMS-I-057	6.09							
Room 20	Sink	7/8/2016	ATAMS-I-058	2.28							
Room 20	Fountain	7/8/2016	ATAMS-I-059	0.76							
Room 21	Sink	7/8/2016	ATAMS-I-060	21.40	9/8/2016	ATAMS-F-066	1.19	Decommissioned.	Decommissioned.	Decommissioned.	Decommissioned.
Room 21	Fountain	7/8/2016	ATAMS-I-061	ND							
Staff Room Refrigerator - In Freezer	Ice Machine	10/8/2016	ATAMS-I-067	1.13							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Report Date: 11/23/2016