

Eugene School District 4J

Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Buena Vista Spanish Immersion Elementary School											
Room 22	Fountain	7/1/2016	BVES-I-001	9.17							
Room 22	Sink	7/1/2016	BVES-I-002	16.80							
Room 23	Sink	7/1/2016	BVES-I-003	13.00							
North Wing Corridor - East end	Fountain	7/1/2016	BVES-I-004	2.20							
Room 21	Fountain	7/1/2016	BVES-I-005	4.24							
Room 21	Sink	7/1/2016	BVES-I-006	5.05							
Room 20	Fountain	7/1/2016	BVES-I-007	4.30							
Room 20	Sink	7/1/2016	BVES-I-008	2.72							
Room 18	Fountain	7/1/2016	BVES-I-009	0.29							
Room 18	Sink	7/1/2016	BVES-I-010	7.18							
Room 19	Fountain	7/1/2016	BVES-I-011	11.00							
Room 19	Sink	7/1/2016	BVES-I-012	12.20							
Room 17	Fountain	7/1/2016	BVES-I-013	7.78							
Room 17	Sink	7/1/2016	BVES-I-014	16.40							
Room 16	Fountain	7/1/2016	BVES-I-015	0.32							
Room 16	Sink	7/1/2016	BVES-I-016	4.47							
Room 15	Fountain	7/1/2016	BVES-I-017	7.50							
Room 15	Sink	7/1/2016	BVES-I-018	9.40							
Room 14	Fountain	7/1/2016	BVES-I-019	7.04							
Room 14	Sink	7/1/2016	BVES-I-020	0.67							
Music Room	Fountain	7/1/2016	BVES-I-021	0.46							
Music Room	Sink	7/1/2016	BVES-I-022	0.89							
North Wing Boys Restroom (North Sink)	Sink	7/1/2016	BVES-I-023	0.68							
North Wing Boys Restroom (South Sink)	Sink	7/1/2016	BVES-I-024	1.36							
North Wing Girls Restroom (South Sink)	Sink	7/1/2016	BVES-I-025	0.90							
North Wing Girls Restroom (North Sink)	Sink	7/1/2016	BVES-I-026	0.57							
North Wing Corridor - West End	Fountain	7/1/2016	BVES-I-027	0.38							
Kitchen Restroom	Sink	7/1/2016	BVES-I-028	1.09							
Kitchen Veggie/Fruit Sink	Sink	7/1/2016	BVES-I-029	1.31							
Kitchen Dishwasher Sink	Sprayer	7/1/2016	BVES-I-030	2.35							
Kitchen Handwash Sink	Sink	7/1/2016	BVES-I-031	0.81							
Cafeteria	Fountain	7/1/2016	BVES-I-032	1.39							
Gym Restroom	Sink	7/1/2016	BVES-I-033	1.21							
Gym Workroom	Fountain	7/1/2016	BVES-I-034	0.88							
Gym Workroom	Sink	7/1/2016	BVES-I-035	0.31							
Staff Restroom	Sink	7/1/2016	BVES-I-036	2.39							
Instructional Material Center	Sink	7/1/2016	BVES-I-037	110.00	8/29/2016	BVES-F-075	ND	9/2/2016	9/7/2016	BVES-I-082	6.27
Staff Lounge	Filter Faucet	7/1/2016	BVES-I-038	0.42							
Staff Lounge	Sink	7/1/2016	BVES-I-039	0.55							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J

Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Buena Vista Spanish Immersion Elementary School											
Staff Lounge	Insta-Hot	7/1/2016	BVES-I-040	ND							
Health Room	Sink	7/1/2016	BVES-I-041	1.24							
Health Room Restroom	Sink	7/1/2016	BVES-I-042	1.32							
Administrative Staff Restroom	Sink	7/1/2016	BVES-I-043	0.43							
South Wing Corridor East End	Fountain	7/1/2016	BVES-I-044	61.50	8/29/2016	BVES-F-076	15.20	9/2/2016	9/7/2016	BVES-I-083	8.13
South Wing East End Boys Restroom	Sink	7/1/2016	BVES-I-045	28.00	8/29/2016	BVES-F-077	1.40	9/2/2016	9/7/2016	BVES-I-084	1.15
South Wing East End Girls Restroom	Sink	7/1/2016	BVES-I-046	1.69							
Room 12	Fountain	7/1/2016	BVES-I-047	35.50	8/29/2016	BVES-F-078	2.10	9/2/2016	9/7/2016	BVES-I-085	ND
Room 12	Sink	7/1/2016	BVES-I-048	54.40	8/29/2016	BVES-F-079	2.37	9/2/2016	9/7/2016	BVES-I-086	6.52
Room 11	Fountain	7/1/2016	BVES-I-049	8.06							
Room 11	Sink	7/1/2016	BVES-I-050	15.90							
Room 10	Fountain	7/1/2016	BVES-I-051	30.10	8/29/2016	BVES-F-080	1.90	9/2/2016	9/7/2016	BVES-I-087	1.21
Room 10	Sink	7/1/2016	BVES-I-052	44.30	8/29/2016	BVES-F-081	2.39	9/2/2016	9/7/2016	BVES-I-088	2.82
Room 9	Fountain	7/1/2016	BVES-I-053	0.45							
Room 9	Sink	7/1/2016	BVES-I-054	4.53							
Room 8	Sink	7/1/2016	BVES-I-055	4.09							
Room 7	Sink	7/1/2016	BVES-I-056	0.75							
South Wing Corridor Center	Fountain	7/1/2016	BVES-I-057	7.79							
Room 6	Fountain	7/1/2016	BVES-I-058	1.16							
Room 6 Restroom	Sink	7/1/2016	BVES-I-059	3.21							
Room 6 Restroom	Sink	7/1/2016	BVES-I-060	1.24							
Room 5	Sink	7/1/2016	BVES-I-061	3.68							
Room 4	Fountain	7/1/2016	BVES-I-062	0.41							
Room 4	Sink	7/1/2016	BVES-I-063	2.12							
Room 3	Sink	7/1/2016	BVES-I-064	1.00							
Room 3	Fountain	7/1/2016	BVES-I-065	1.33							
Room 2	Fountain	7/1/2016	BVES-I-066	1.43							
Room 2 Restroom	Sink	7/1/2016	BVES-I-067	2.68							
Room 2 Restroom	Sink	7/1/2016	BVES-I-068	1.73							
Room 1	Sink	7/1/2016	BVES-I-069	3.14							
South Wing West End Boys Restroom (North Sink)	Sink	7/1/2016	BVES-I-070	1.88							
South Wing West End Boys Restroom (South Sink)	Sink	7/1/2016	BVES-I-071	0.61							
South Wing West End Boys Restroom (North Sink)	Sink	7/1/2016	BVES-I-072	4.07							
South Wing West End Girls Restroom (South Sink)	Sink	7/1/2016	BVES-I-073	3.11							
South Wing West End	Fountain	7/1/2016	BVES-I-074	2.64							
Outside Playground East Side	Fountain	9/22/2016	BVES-I-089	3.20							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.