

Eugene School District 4J
Water Quality: Lead Testing Results

| Eugene School District 4J - Location | Fixture Type | First Draw | | | Flushed Draw | | | New Fixture First Draw | | | | Follow Up - New Fixture Draw | | | |
|---|--------------|--------------|-------------|--------------|--------------|-------------|--------------|------------------------|--------------|-------------|--------------|---|--------------|-------------|--------------|
| | | Date Sampled | Sample ID # | Result (ppb) | Date Sampled | Sample ID # | Result (ppb) | Fixture Replaced | Date Sampled | Sample ID # | Result (ppb) | Additional Action | Date Sampled | Sample ID # | Result (ppb) |
| Churchill High School | | | | | | | | | | | | | | | |
| Kitchen Produce Sink | Sink | 7/12/2016 | CHS-I-001 | 0.60 | | | | | | | | | | | |
| Kitchen Handwash | Sink | 7/12/2016 | CHS-I-002 | 3.89 | | | | | | | | | | | |
| Kitchen Office Restroom | Sink | 7/12/2016 | CHS-I-003 | 21.30 | 9/9/2016 | CHS-F-182 | 1.54 | 10/28/2016 | 11/2/2016 | CHS-I-205 | 2.26 | | | | |
| Kitchen Dishwashing Area (Wash) | Sink | 7/12/2016 | CHS-I-004 | 1.44 | | | | | | | | | | | |
| Kitchen Dishwashing Area (Rinse) | Sink | 7/12/2016 | CHS-I-005 | 3.40 | | | | | | | | | | | |
| Kitchen Dishwashing Area (Sanitize) | Sink | 7/12/2016 | CHS-I-006 | 5.06 | | | | | | | | | | | |
| Kitchen Dishwashing Area (Eyewash) | Sink | 7/12/2016 | CHS-I-007 | 16.80 | | | | | | | | | | | |
| Custodian Office Restroom | Sink | 7/12/2016 | CHS-I-008 | 1.08 | | | | | | | | | | | |
| Kitchen Area Staff Lounge | Sink | 7/12/2016 | CHS-I-009 | 4.47 | | | | | | | | | | | |
| Cafeteria (West) | Fountain | 7/12/2016 | CHS-I-010 | ND | | | | | | | | | | | |
| Cafeteria (East) | Fountain | 7/12/2016 | CHS-I-011 | 0.43 | | | | | | | | | | | |
| Gym East End | Fountain | 7/12/2016 | CHS-I-012 | 0.20 | | | | | | | | | | | |
| Gym Men's Restroom (North) | Sink | 7/12/2016 | CHS-I-013 | 1.00 | | | | | | | | | | | |
| Gym Men's Restroom (Center) | Sink | 7/12/2016 | CHS-I-014 | 0.71 | | | | | | | | | | | |
| Gym Men's Restroom (South) | Sink | 7/12/2016 | CHS-I-015 | 0.50 | | | | | | | | | | | |
| Men's Locker Room | Fountain | 7/12/2016 | CHS-I-016 | 0.66 | | | | | | | | | | | |
| Men's Locker Room Restroom (East) | Sink | 7/12/2016 | CHS-I-017 | 0.84 | | | | | | | | | | | |
| Men's Locker Room Restroom (West) | Sink | 7/12/2016 | CHS-I-018 | 1.93 | | | | | | | | | | | |
| Men's Locker Room Coaches Shower Restroom | Sink | 7/12/2016 | CHS-I-019 | 5.16 | | | | | | | | | | | |
| Gym West End (North) | Fountain | 7/12/2016 | CHS-I-020 | 0.26 | | | | | | | | | | | |
| Training Room West Wall | Sink | 7/12/2016 | CHS-I-021 | 15.00 | | | | | | | | | | | |
| Training Room North Wall | Sink | 7/12/2016 | CHS-I-022 | 1.10 | | | | | | | | | | | |
| Training Room Ice Machine | Ice Machine | 7/12/2016 | CHS-I-023 | 0.20 | | | | | | | | | | | |
| Athletic Equipment Area Restroom | Sink | 7/12/2016 | CHS-I-024 | 0.43 | | | | | | | | | | | |
| Athletic Equipment Area | Fountain | 7/12/2016 | CHS-I-025 | 0.99 | | | | | | | | | | | |
| Gym West End (South) | Fountain | 7/12/2016 | CHS-I-026 | 0.38 | | | | | | | | | | | |
| Women's Locker Room (North) | Fountain | 7/12/2016 | CHS-I-027 | 0.32 | | | | | | | | | | | |
| Women's Locker Room North Wall (West) | Sink | 7/12/2016 | CHS-I-028 | 5.96 | | | | | | | | | | | |
| Women's Locker Room North Wall (East) | Sink | 7/12/2016 | CHS-I-029 | 2.06 | | | | | | | | | | | |
| Women's Locker Room South Wall (East) | Sink | 7/12/2016 | CHS-I-030 | 2.44 | | | | | | | | | | | |
| Women's Locker Room South Wall (West) | Sink | 7/12/2016 | CHS-I-031 | 4.84 | | | | | | | | | | | |
| Women's Locker Room (South) | Fountain | 7/12/2016 | CHS-I-032 | 1.10 | | | | | | | | | | | |
| Women's Locker Room Coaches Office Restroom | Sink | 7/12/2016 | CHS-I-033 | 3.80 | | | | | | | | | | | |
| Gym Women's Restroom (North) | Sink | 7/12/2016 | CHS-I-034 | 0.94 | | | | | | | | | | | |
| Gym Women's Restroom (center) | Sink | 7/12/2016 | CHS-I-035 | 0.72 | | | | | | | | | | | |
| Gym Women's Restroom (South) | Sink | 7/12/2016 | CHS-I-036 | 0.67 | | | | | | | | | | | |
| Gym Snack Shop | Sink | 7/12/2016 | CHS-I-037 | 5.41 | | | | | | | | | | | |
| Library IMC | Sink | 7/12/2016 | CHS-I-038 | 0.66 | | | | | | | | | | | |
| Corridor outside Library (North) | Fountain | 7/12/2016 | CHS-I-039 | 0.33 | | | | | | | | | | | |
| Corridor outside Library (South) | Fountain | 7/12/2016 | CHS-I-040 | 0.48 | | | | | | | | | | | |
| Girls Restroom Between Library and F Wing (South) | Sink | 7/12/2016 | CHS-I-041 | 1.42 | | | | | | | | | | | |
| Girls Restroom Between Library and F Wing (North) | Sink | 7/12/2016 | CHS-I-042 | 1.33 | | | | | | | | | | | |
| Boys Restroom between Library and F Wing (South) | Sink | 7/12/2016 | CHS-I-043 | 1.23 | | | | | | | | | | | |
| Boys Restroom between Library and F Wing (South) | Sink | 7/12/2016 | CHS-I-044 | 0.67 | | | | | | | | | | | |
| Corridor at West end of F wing (South) | Fountain | 7/12/2016 | CHS-I-045 | 0.23 | | | | | | | | | | | |
| Corridor at West End of F Wing (North) | Fountain | 7/12/2016 | CHS-I-046 | 0.58 | | | | | | | | | | | |
| Room K3 Demonstration Table | Sink | 7/12/2016 | CHS-I-047 | 33.70 | 9/19/2016 | CHS-F-203 | 1.01 | 10/28/2016 | 11/2/2016 | CHS-I-219 | 2.56 | | | | |
| Room K3 West Wall (South) | Sink | 7/12/2016 | CHS-I-048 | 38.00 | 9/9/2016 | CHS-F-186 | 8.39 | 10/28/2016 | 11/2/2016 | CHS-I-223 | 12.80 | | | | |
| Room K3 West Wall (center) | Sink | 7/12/2016 | CHS-I-049 | 66.80 | 9/9/2016 | CHS-F-187 | 7.40 | 10/28/2016 | 11/2/2016 | CHS-I-224 | 6.10 | | | | |
| Room K3 West Wall (North) | Sink | 7/12/2016 | CHS-I-050 | 35.70 | 9/9/2016 | CHS-F-188 | 2.75 | 10/28/2016 | 11/2/2016 | CHS-I-225 | 19.20 | | | | |
| Room K3 East Wall (North) | Sink | 7/12/2016 | CHS-I-051 | 25.20 | 9/9/2016 | CHS-F-185 | 8.27 | 10/28/2016 | 11/2/2016 | CHS-I-222 | 62.60 | New Stops, nipples, and removed brass mixing valve. | 2/10/2017 | CHS-I-227 | ND |
| Room K3 East Wall (center) | Sink | 7/12/2016 | CHS-I-052 | 78.40 | 9/9/2016 | CHS-F-184 | 6.35 | 10/28/2016 | 11/2/2016 | CHS-I-221 | 8.45 | | | | |
| Room K3 East Wall (South) | Sink | 7/12/2016 | CHS-I-053 | 62.40 | 9/9/2016 | CHS-F-183 | 22.00 | 10/28/2016 | 11/2/2016 | CHS-I-220 | 15.70 | | | | |
| Room K5 | Sink | 7/12/2016 | CHS-I-054 | 6.21 | | | | | | | | | | | |
| Room K7 Demonstration table | Sink | 7/12/2016 | CHS-I-055 | 222.00 | 9/9/2016 | CHS-F-197 | 10.60 | 10/28/2016 | 11/2/2016 | CHS-I-209 | 3.82 | | | | |

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

| Eugene School District 4J - Location | Fixture Type | First Draw | | | Flushed Draw | | | New Fixture First Draw | | | | Follow Up - New Fixture Draw | | |
|---|-----------------|--------------|-------------|--------------|--------------|-------------|--------------|------------------------|--------------|-------------|--------------|------------------------------|--------------|-------------|
| | | Date Sampled | Sample ID # | Result (ppb) | Date Sampled | Sample ID # | Result (ppb) | Fixture Replaced | Date Sampled | Sample ID # | Result (ppb) | Additional Action | Date Sampled | Sample ID # |
| Churchill High School | | | | | | | | | | | | | | |
| Room K7 West Wall (South) | Sink | 7/12/2016 | CHS-I-056 | 11.70 | | | | | | | | | | |
| Room K7 West Wall (center) | Sink | 7/12/2016 | CHS-I-057 | 10.20 | | | | | | | | | | |
| Room K7 West Wall (North) | Sink | 7/12/2016 | CHS-I-058 | 10.80 | 9/9/2016 | CHS-F-198 | 1.54 | | | | | | | |
| Room K7 East Wall (North) | Sink | 7/12/2016 | CHS-I-059 | 7.68 | | | | | | | | | | |
| Room K7 East Wall (center) | Sink | 7/12/2016 | CHS-I-060 | 10.80 | | | | | | | | | | |
| Room K7 East Wall (South) | Sink | 7/12/2016 | CHS-I-061 | 21.10 | 9/30/2016 | CHS-F-204 | 2.38 | 10/28/2016 | 11/2/2016 | CHS-I-210 | 3.61 | | | |
| Room K8 Demonstration Table | Sink | 7/12/2016 | CHS-I-062 | 9.02 | | | | | | | | | | |
| Room K8 South Wall (East) | Sink | 7/12/2016 | CHS-I-063 | 7.19 | | | | | | | | | | |
| Room K8 South Wall (center) | Sink | 7/12/2016 | CHS-I-064 | 8.69 | | | | | | | | | | |
| Room K8 South Wall (West) | Sink | 7/12/2016 | CHS-I-065 | 6.74 | | | | | | | | | | |
| Room K8 North Wall (West) | Sink | 7/12/2016 | CHS-I-066 | 10.70 | | | | | | | | | | |
| Room K8 North Wall (center) | Sink | 7/12/2016 | CHS-I-067 | 7.59 | | | | | | | | | | |
| Room K8 North Wall (East) | Sink | 7/12/2016 | CHS-I-068 | 9.56 | | | | | | | | | | |
| Room K4 Demonstration Table | Sink | 7/12/2016 | CHS-I-069 | 31.40 | 9/9/2016 | CHS-F-192 | 4.37 | 10/28/2016 | 11/2/2016 | CHS-I-211 | 3.81 | | | |
| Room K6 | Sink | 7/12/2016 | CHS-I-070 | 33.80 | 9/9/2016 | CHS-F-196 | 1.48 | 10/28/2016 | 11/2/2016 | CHS-I-212 | 2.91 | | | |
| Room K4 North Wall (West) | Sink | 7/12/2016 | CHS-I-071 | 45.70 | 9/9/2016 | CHS-F-191 | 6.16 | 10/28/2016 | 11/2/2016 | CHS-I-213 | 4.47 | | | |
| Room K4 North Wall (center) | Sink | 7/12/2016 | CHS-I-072 | 41.20 | 9/9/2016 | CHS-F-190 | 2.52 | 10/28/2016 | 11/2/2016 | CHS-I-214 | 2.71 | | | |
| Room K4 North Wall (East) | Sink | 7/12/2016 | CHS-I-073 | 46.30 | 9/9/2016 | CHS-F-189 | 3.23 | 10/28/2016 | 11/2/2016 | CHS-I-215 | 2.49 | | | |
| Room K4 South Wall (East) | Sink | 7/12/2016 | CHS-I-074 | 30.70 | 9/9/2016 | CHS-F-193 | 2.93 | 10/28/2016 | 11/2/2016 | CHS-I-216 | 2.42 | | | |
| Room K4 South Wall (center) | Sink | 7/12/2016 | CHS-I-075 | 34.70 | 9/9/2016 | CHS-F-194 | 2.49 | 10/28/2016 | 11/2/2016 | CHS-I-217 | 4.44 | | | |
| Room K4 South Wall (West) | Sink | 7/12/2016 | CHS-I-076 | 48.40 | 9/9/2016 | CHS-F-195 | 1.74 | 10/28/2016 | 11/2/2016 | CHS-I-218 | 2.19 | | | |
| J Wing North Corridor | Fountain | 7/12/2016 | CHS-I-077 | ND | | | | | | | | | | |
| Room J24 | Sink | 7/12/2016 | CHS-I-078 | 1.78 | | | | | | | | | | |
| Student Store | Sink | 7/12/2016 | CHS-I-079 | 217.00 | 9/9/2016 | CHS-F-199 | ND | 10/28/2016 | 11/2/2016 | CHS-I-206 | 2.57 | | | |
| Corridor East of J Wing (North) | Fountain | 7/12/2016 | CHS-I-080 | 0.33 | | | | | | | | | | |
| Corridor East of J Wing (South) | Fountain | 7/12/2016 | CHS-I-081 | 0.41 | | | | | | | | | | |
| Girls Restroom between J & H Wings (South) | Sink | 7/12/2016 | CHS-I-082 | 0.84 | | | | | | | | | | |
| Girls Restroom between J & H Wings (center) | Sink | 7/12/2016 | CHS-I-083 | 0.66 | | | | | | | | | | |
| Girls Restroom between J & H Wings (North) | Sink | 7/12/2016 | CHS-I-084 | 0.49 | | | | | | | | | | |
| Boys Restroom between J & H Wings (North) | Sink | 7/12/2016 | CHS-I-085 | 0.60 | | | | | | | | | | |
| Boys Restroom between J & H Wings (center) | Sink | 7/12/2016 | CHS-I-086 | 0.50 | | | | | | | | | | |
| Boys Restroom between J & H Wings (South) | Sink | 7/12/2016 | CHS-I-087 | 0.49 | | | | | | | | | | |
| J Wing South Corridor | Fountain | 7/12/2016 | CHS-I-088 | 0.62 | | | | | | | | | | |
| International High School Staff | Sink | 7/12/2016 | CHS-I-089 | 2.38 | | | | | | | | | | |
| H Wing South Corridor | Fountain | 7/12/2016 | CHS-I-090 | 0.33 | | | | | | | | | | |
| H Wing Math Office | Sink | 7/12/2016 | CHS-I-091 | 0.89 | | | | | | | | | | |
| H Wing Science Office | Sink | 7/12/2016 | CHS-I-092 | 1.17 | | | | | | | | | | |
| F Wing Computer Services | Sink | 7/12/2016 | CHS-I-093 | 3.17 | | | | | | | | | | |
| F Wing South Corridor | Fountain | 7/12/2016 | CHS-I-094 | 0.27 | | | | | | | | | | |
| F Wing 2nd Language Office | Sink | 7/12/2016 | CHS-I-095 | 2.99 | | | | | | | | | | |
| Room F55 | Sink | 7/12/2016 | CHS-I-096 | 4.61 | | | | | | | | | | |
| Laundry Room adjoining Room F55 | Sink | 7/12/2016 | CHS-I-097 | 3.12 | | | | | | | | | | |
| Room F49 North Wall | Sink | 7/12/2016 | CHS-I-098 | 5.37 | | | | | | | | | | |
| Room F49 North Island (North) | Sink | 7/12/2016 | CHS-I-099 | 4.37 | | | | | | | | | | |
| Room F49 North Island (South) | Sink | 7/12/2016 | CHS-I-100 | 5.60 | | | | | | | | | | |
| Room F49 South Island (North) | Sink | 7/12/2016 | CHS-I-101 | 3.78 | | | | | | | | | | |
| Room F49 South Island (South) | Sink | 7/12/2016 | CHS-I-102 | 3.76 | | | | | | | | | | |
| Room F49 South Wall | Sink | 7/12/2016 | CHS-I-103 | 5.01 | | | | | | | | | | |
| Room F49 West Wall | Sink | 7/12/2016 | CHS-I-104 | 2.34 | | | | | | | | | | |
| Room F49 Office | Sink | 7/12/2016 | CHS-I-105 | 4.25 | | | | | | | | | | |
| Room F37 | Sink | 7/12/2016 | CHS-I-106 | 5.27 | | | | | | | | | | |
| F Wing North Corridor | Fountain | 7/12/2016 | CHS-I-107 | 0.78 | | | | | | | | | | |
| Administrative Wing Staff Lounge | Filtered Faucet | 7/12/2016 | CHS-I-108 | ND | | | | | | | | | | |
| Administrative Wing Staff Lounge | Sink | 7/12/2016 | CHS-I-109 | 0.51 | | | | | | | | | | |
| Health Center | Sink | 7/12/2016 | CHS-I-110 | 0.29 | | | | | | | | | | |
| Health Center North Restroom | Sink | 7/12/2016 | CHS-I-111 | 4.79 | | | | | | | | | | |

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

| Eugene School District 4J - Location | Fixture Type | First Draw | | | Flushed Draw | | | New Fixture First Draw | | | | Follow Up - New Fixture Draw | | |
|--|--------------|--------------|-------------|--------------|--------------|-------------|--------------|------------------------|--------------|-------------|--------------|------------------------------|--------------|-------------|
| | | Date Sampled | Sample ID # | Result (ppb) | Date Sampled | Sample ID # | Result (ppb) | Fixture Replaced | Date Sampled | Sample ID # | Result (ppb) | Additional Action | Date Sampled | Sample ID # |
| Churchill High School | | | | | | | | | | | | | | |
| Health Center North Exam Room | Sink | 7/12/2016 | CHS-I-112 | 4.32 | | | | | | | | | | |
| Health Center South Restroom | Sink | 7/12/2016 | CHS-I-113 | 1.96 | | | | | | | | | | |
| Health Center South Exam Room | Sink | 7/12/2016 | CHS-I-114 | 9.82 | | | | | | | | | | |
| Administrative Staff All Gender Restroom (North) | Sink | 7/12/2016 | CHS-I-115 | 4.00 | | | | | | | | | | |
| Administrative Staff All Gender Restroom (South) | Sink | 7/12/2016 | CHS-I-116 | 2.55 | | | | | | | | | | |
| Administrative Staff Women's Restroom (South) | Sink | 7/12/2016 | CHS-I-117 | 1.27 | | | | | | | | | | |
| Administrative Staff Women's Restroom (North) | Sink | 7/12/2016 | CHS-I-118 | 0.66 | | | | | | | | | | |
| Administrative Wing Corridor | Fountain | 7/12/2016 | CHS-I-119 | 0.66 | | | | | | | | | | |
| Administrative Wing Work Room | Sink | 7/12/2016 | CHS-I-120 | 1.70 | | | | | | | | | | |
| A Wing Women's Restroom (North) | Sink | 7/12/2016 | CHS-I-121 | 1.25 | | | | | | | | | | |
| A Wing Women's Restroom (South) | Sink | 7/12/2016 | CHS-I-122 | 0.90 | | | | | | | | | | |
| A Wing West Corridor | Fountain | 7/12/2016 | CHS-I-123 | 0.42 | | | | | | | | | | |
| A Wing Men's Restroom (West) | Sink | 7/12/2016 | CHS-I-124 | 1.01 | | | | | | | | | | |
| A Wing Men's Restroom (East) | Sink | 7/12/2016 | CHS-I-125 | 0.75 | | | | | | | | | | |
| Room DB | Fountain | 7/12/2016 | CHS-I-126 | 0.28 | | | | | | | | | | |
| Room D2 | Fountain | 7/12/2016 | CHS-I-127 | 0.38 | | | | | | | | | | |
| Room D2 | Sink | 7/12/2016 | CHS-I-128 | 1.81 | | | | | | | | | | |
| Room B1 (West) | Sink | 7/12/2016 | CHS-I-129 | 10.40 | | | | | | | | | | |
| Room B1 (East) | Sink | 7/12/2016 | CHS-I-130 | 752.00 | 9/9/2016 | CHS-F-202 | 1.77 | 10/28/2016 | 11/2/2016 | CHS-I-226 | ND | | | |
| Room B4 (East) | Sink | 7/12/2016 | CHS-I-131 | 2.30 | | | | | | | | | | |
| Room B4 (West) | Sink | 7/12/2016 | CHS-I-132 | 0.84 | | | | | | | | | | |
| Room C9 Sink Island (Southwest) | Sink | 7/12/2016 | CHS-I-133 | 0.64 | | | | | | | | | | |
| Room C9 Sink Island (Southeast) | Sink | 7/12/2016 | CHS-I-134 | 1.17 | | | | | | | | | | |
| Room C9 Sink Island (Northwest) | Sink | 7/12/2016 | CHS-I-135 | 0.98 | | | | | | | | | | |
| Room C9 Sink Island (Northeast) | Sink | 7/12/2016 | CHS-I-136 | 0.27 | | | | | | | | | | |
| Room C8 Near Door | Sink | 7/12/2016 | CHS-I-137 | 10.90 | | | | | | | | | | |
| Room C8 Northeast of Door | Sink | 7/12/2016 | CHS-I-138 | 9.31 | | | | | | | | | | |
| C Wing Corridor | Fountain | 7/12/2016 | CHS-I-139 | 1.14 | | | | | | | | | | |
| CA Wing South Corridor (Upper) | Fountain | 7/12/2016 | CHS-I-140 | ND | | | | | | | | | | |
| CA Wing South Corridor (Lower) | Fountain | 7/12/2016 | CHS-I-141 | ND | | | | | | | | | | |
| CA Wing Women's Restroom (East) | Sink | 7/12/2016 | CHS-I-142 | 0.46 | | | | | | | | | | |
| CA Wing Women's Restroom (center) | Sink | 7/12/2016 | CHS-I-143 | 0.38 | | | | | | | | | | |
| CA Wing Women's Restroom (West) | Sink | 7/12/2016 | CHS-I-144 | 0.70 | | | | | | | | | | |
| CA Wing Men's Restroom (East) | Sink | 7/12/2016 | CHS-I-145 | 0.56 | | | | | | | | | | |
| CA Wing Men's Restroom (center) | Sink | 7/12/2016 | CHS-I-146 | 0.40 | | | | | | | | | | |
| CA Wing Men's Restroom (West) | Sink | 7/12/2016 | CHS-I-147 | 0.48 | | | | | | | | | | |
| CA Wing Meeting Room | Sink | 7/12/2016 | CHS-I-148 | 0.84 | | | | | | | | | | |
| CA Wing Room 112 | Sink | 7/12/2016 | CHS-I-149 | 0.36 | | | | | | | | | | |
| CA Wing Center for Natural Resources | Sink | 7/12/2016 | CHS-I-150 | 0.36 | | | | | | | | | | |
| Dental Clinic Restroom | Sink | 7/12/2016 | CHS-I-151 | 0.36 | | | | | | | | | | |
| Dental Clinic Kitchen | Sink | 7/12/2016 | CHS-I-152 | 1.10 | | | | | | | | | | |
| Dental Clinic North Exam Room | Sink | 7/12/2016 | CHS-I-153 | 1.11 | | | | | | | | | | |
| Dental Clinic South Exam Room | Sink | 7/12/2016 | CHS-I-154 | 3.63 | | | | | | | | | | |
| Corridor Outside Room B1 | Fountain | 7/15/2016 | CHS-I-155 | ND | | | | | | | | | | |
| Backstage Utility Sink | Sink | 7/15/2016 | CHS-I-156 | 1.44 | | | | | | | | | | |
| Kitchen Dish Room North Wall | Sprayer | 7/15/2016 | CHS-I-157 | 1.07 | | | | | | | | | | |
| Kitchen Dish Room West Wall | Sprayer | 7/15/2016 | CHS-I-158 | 2.69 | | | | | | | | | | |
| Corridor West of H Wing South Fixture | Fountain | 7/15/2016 | CHS-I-159 | 1.03 | | | | | | | | | | |
| Corridor West of H Wing North Fixture | Fountain | 7/15/2016 | CHS-I-160 | ND | | | | | | | | | | |
| H Wing Staff Women's Restroom North Fixture | Sink | 7/15/2016 | CHS-I-161 | 1.22 | | | | | | | | | | |
| H Wing Staff Women's Restroom South Fixture | Sink | 7/15/2016 | CHS-I-162 | 7.36 | | | | | | | | | | |
| H Wing Staff Men's Restroom South Fixture | Sink | 7/15/2016 | CHS-I-163 | 9.73 | | | | | | | | | | |
| H Wing Staff Men's Restroom North Fixture | Sink | 7/15/2016 | CHS-I-164 | 2.35 | | | | | | | | | | |
| Science Lab Storage Room | Sink | 7/15/2016 | CHS-I-165 | 9.49 | | | | | | | | | | |
| Science Lab Chemical Storage Room | Sink | 7/15/2016 | CHS-I-166 | 3.65 | | | | | | | | | | |
| Science Lab Textbook Storage Room | Sink | 7/15/2016 | CHS-I-167 | 8.58 | | | | | | | | | | |

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

| Eugene School District 4J - Location | Fixture Type | First Draw | | | Flushed Draw | | | New Fixture First Draw | | | | Follow Up - New Fixture Draw | | | |
|--|--------------|--------------|-------------|--------------|--------------|-------------|--------------|------------------------|--------------|-------------|--------------|------------------------------|--------------|-------------|--------------|
| | | Date Sampled | Sample ID # | Result (ppb) | Date Sampled | Sample ID # | Result (ppb) | Fixture Replaced | Date Sampled | Sample ID # | Result (ppb) | Additional Action | Date Sampled | Sample ID # | Result (ppb) |
| Churchill High School | | | | | | | | | | | | | | | |
| Room H21 South Wall | Sink | 7/15/2016 | CHS-I-168 | 1.46 | | | | | | | | | | | |
| Room H21 West Wall South Island | Sink | 7/15/2016 | CHS-I-169 | 3.90 | | | | | | | | | | | |
| Room H21 West Wall South Center Island | Sink | 7/15/2016 | CHS-I-170 | 11.30 | | | | | | | | | | | |
| Room H21 West Wall North Center Island | Sink | 7/15/2016 | CHS-I-171 | 8.57 | | | | | | | | | | | |
| Room H21 West Wall North Island | Sink | 7/15/2016 | CHS-I-172 | 3.54 | | | | | | | | | | | |
| Room H21 East Wall North Island | Sink | 7/15/2016 | CHS-I-173 | 5.37 | | | | | | | | | | | |
| Room H21 East Wall Demo Table | Sink | 7/15/2016 | CHS-I-174 | 12.40 | | | | | | | | | | | |
| Room H21 East Wall South Island | Sink | 7/15/2016 | CHS-I-175 | 3.64 | | | | | | | | | | | |
| Room H20 | Sink | 7/15/2016 | CHS-I-176 | 8.16 | | | | | | | | | | | |
| Room H19 South Wall | Sink | 7/15/2016 | CHS-I-177 | 6.54 | | | | | | | | | | | |
| Room H19 Demo Table | Sink | 7/15/2016 | CHS-I-178 | 53.90 | 9/9/2016 | CHS-F-201 | 1.55 | 10/28/2016 | 11/2/2016 | CHS-I-208 | 120.00 | Source Decommissioned | N/A | N/A | N/A |
| Room H19 East Wall North Island | Sink | 7/15/2016 | CHS-I-179 | 56.20 | 9/9/2016 | CHS-F-200 | 2.38 | 10/28/2016 | 11/2/2016 | CHS-I-207 | 144.00 | Source Decommissioned | N/A | N/A | N/A |
| CHS Stadium Hydrant | Hose Bib | 8/3/2016 | CHS-I-180 | 9.27 | | | | | | | | | | | |
| Kitchen South Side of Middle Partition | Ice Machine | 8/5/2016 | CHS-I-181 | ND | | | | | | | | | | | |

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.