

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Howard Elementary School (NEW)											
Kitchen Sprayer South Wall East	Sprayer	8/26/2016	NHES-I-001	8.12							
Kitchen Dishwash sink South Wall (Left)	Sink	8/26/2016	NHES-I-002	2.02							
Kitchen Dishwash sink South Wall (Right)	Sink	8/26/2016	NHES-I-003	ND							
Kitchen Ice Machine	Ice Machine	8/26/2016	NHES-I-004	ND							
Kitchen Handwash Sink on Island (West)	S	8/26/2016	NHES-I-005	ND							
Kitchen Double Basin Sink on Island (Center)	Sink	8/26/2016	NHES-I-006	ND							
Kitchen North Wall Handwash	Sink	8/26/2016	NHES-I-007	ND							
Kitchen On Mixer	Sink	8/26/2016	NHES-I-008	1.06							
Cafeteria East Wall (Left Upper)	Fountain	8/26/2016	NHES-I-009	ND							
Cafeteria East Wall (Right Lower)	Fountain	8/26/2016	NHES-I-010	ND							
Cafeteria East Wall Water Dispenser	Bottle Filler	8/26/2016	NHES-I-011	ND							
Cafeteria East Wall Handwash (North side)	Sink	8/26/2016	NHES-I-012	2.16							
Cafeteria East Wall Handwash (South Side)	Sink	8/26/2016	NHES-I-013	2.14							
Room 138 West Wall	Sink	8/26/2016	NHES-I-014	ND							
Staff Room 106 West Wall	Sink	8/26/2016	NHES-I-015	ND							
Staff Room 106 West Wall	Insta-Hot	8/26/2016	NHES-I-016	ND							
Staff Room 106 Refrigerator - In Door (North left)	Dispencer	8/26/2016	NHES-I-017	ND							
Staff Room across from 105	Sink	8/26/2016	NHES-I-018	ND							
Staff Room 106 Refrigerator - In Door (South right)	Dispencer	8/26/2016	NHES-I-019	ND							
Room 112 North Wall	Sink	8/26/2016	NHES-I-020	ND							
Room 110	Sink	8/26/2016	NHES-I-021	ND							
Restroom South of Room 110	Sink	8/26/2016	NHES-I-022	ND							
Room 123	Sink	8/26/2016	NHES-I-023	ND							
Boys Restroom (Left)	Sink	8/26/2016	NHES-I-024	1.31							
Boys Restroom (right)	Sink	8/26/2016	NHES-I-025	1.32							
Girls Restroom (Left)	Sink	8/26/2016	NHES-I-026	1.62							
Girls Restroom (right)	Sink	8/26/2016	NHES-I-027	1.72							
Wheelchair Access All Gender Restroom near Room 132	Sink	8/26/2016	NHES-I-028	ND							
Staff Restroom near Room 132	Sink	8/26/2016	NHES-I-029	ND							
C105	Fountain	8/26/2016	NHES-I-030	ND							
C105	Sink	8/26/2016	NHES-I-031	ND							
C101	Fountain	8/26/2016	NHES-I-032	ND							
C101	Sink	8/26/2016	NHES-I-033	ND							
C103	Fountain	8/26/2016	NHES-I-034	ND							
C103	Sink	8/26/2016	NHES-I-035	ND							
C104	Fountain	8/26/2016	NHES-I-036	ND							
C104	Sink	8/26/2016	NHES-I-037	ND							
Girls Restroom by Room 130 (Left)	Sink	8/26/2016	NHES-I-038	1.30							
Girls Restroom by Room 130 (Right)	Sink	8/26/2016	NHES-I-039	3.19							
Boys Restroom By Room 130 (Left)	Sink	8/26/2016	NHES-I-040	2.29							
Boys Restroom by Room 130 (Right)	Sink	8/26/2016	NHES-I-041	1.74							
Wheelchair Access All Gender Restroom across from Room 130	Sink	8/26/2016	NHES-I-042	ND							
Staff Restroom near Room 130	Sink	8/26/2016	NHES-I-043	ND							
B101	Fountain	8/26/2016	NHES-I-044	ND							
B101	Sink	8/26/2016	NHES-I-045	ND							
B105	Fountain	8/26/2016	NHES-I-046	ND							
B105	Sink	8/26/2016	NHES-I-047	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Howard Elementary School (NEW)											
B102	Fountain	8/26/2016	NHES-I-048	ND							
B102	Sink	8/26/2016	NHES-I-049	ND							
B103	Fountain	8/26/2016	NHES-I-050	ND							
B103	Sink	8/26/2016	NHES-I-051	ND							
B104	Fountain	8/26/2016	NHES-I-052	ND							
B104	Sink	8/26/2016	NHES-I-053	ND							
Boys Restroom by Room 119 (left)	Sink	8/26/2016	NHES-I-054	1.67							
Boys Restroom by Room 119 (right)	Sink	8/26/2016	NHES-I-055	1.12							
Girls Restroom by Room 119 (left)	Sink	8/26/2016	NHES-I-056	1.38							
Girls Restroom by Room 119 (right)	Sink	8/26/2016	NHES-I-057	2.16							
Wheelchair Access All Gender Restroom by Room 119	Sink	8/26/2016	NHES-I-058	ND							
A105	Fountain	8/26/2016	NHES-I-059	1.04							
A105	Sink	8/26/2016	NHES-I-060	1.20							
A101	Fountain	8/26/2016	NHES-I-061	ND							
A101	Sink	8/26/2016	NHES-I-062	ND							
A102	Fountain	8/26/2016	NHES-I-063	ND							
A102	Sink	8/26/2016	NHES-I-064	ND							
A103	Fountain	8/26/2016	NHES-I-065	ND							
A103	Sink	8/26/2016	NHES-I-066	ND							
A104	Fountain	8/26/2016	NHES-I-067	ND							
A104	Sink	8/26/2016	NHES-I-068	ND							
2nd Floor by Room 222 (Upper left)	Fountain	8/26/2016	NHES-I-069	ND							
2nd Floor by Room 222 (Lower right)	Fountain	8/26/2016	NHES-I-070	ND							
2nd Floor by Room 222 Elkay Unit	Bottle Filler	8/26/2016	NHES-I-071	ND							
2nd Floor Restroom 203 Boys (left)	Sink	8/26/2016	NHES-I-072	1.65							
2nd Floor Boys Restroom 203 (right)	Sink	8/26/2016	NHES-I-073	1.76							
2nd Floor Girls Restroom 204 (left)	Sink	8/26/2016	NHES-I-074	2.16							
2nd Floor Girls Restroom 204 (right)	Sink	8/26/2016	NHES-I-075	2.56							
2nd Floor Wheelchair Access All Gender Restroom by Room 217	Sink	8/26/2016	NHES-I-076	ND							
2nd Floor Staff Restroom by Rom 217	Sink	8/26/2016	NHES-I-077	ND							
2nd Floor A205	Fountain	8/26/2016	NHES-I-078	1.55							
2nd Floor A205	Sink	8/26/2016	NHES-I-079	ND							
2nd Floor A201	Fountain	8/26/2016	NHES-I-080	ND							
2nd Floor A201	Sink	8/26/2016	NHES-I-081	ND							
2nd Floor A202	Fountain	8/26/2016	NHES-I-082	ND							
2nd Floor A202	Sink	8/26/2016	NHES-I-083	ND							
2nd Floor A204	Fountain	8/26/2016	NHES-I-084	ND							
2nd Floor A204	Sink	8/26/2016	NHES-I-085	ND							
2nd Floor A203	Fountain	8/26/2016	NHES-I-086	ND							
2nd Floor A203	Sink	8/26/2016	NHES-I-087	ND							
2nd Floor Boys Restroom 217 (left)	Sink	8/26/2016	NHES-I-088	5.04							
2nd Floor Boys Restroom 217 (right)	Sink	8/26/2016	NHES-I-089	4.09							
2nd Floor Girls Restroom 218 (left)	Sink	8/26/2016	NHES-I-090	1.69							
2nd Floor Girls Restroom 218 (right)	Sink	8/26/2016	NHES-I-091	2.47							
2nd Floor Wheelchair Access All Gender Restroom by Room 216	Sink	8/26/2016	NHES-I-092	ND							
2nd Floor Staff Restroom by Room 216	Sink	8/26/2016	NHES-I-093	ND							
2nd Floor C201	Fountain	8/26/2016	NHES-I-094	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Howard Elementary School (NEW)											
2nd Floor C201	Sink	8/26/2016	NHES-I-095	ND							
2nd Floor C205	Fountain	8/26/2016	NHES-I-096	ND							
2nd Floor C205	Sink	8/26/2016	NHES-I-097	ND							
2nd Floor C202	Fountain	8/26/2016	NHES-I-098	ND							
2nd Floor C202	Sink	8/26/2016	NHES-I-099	ND							
2nd Floor C203	Fountain	8/26/2016	NHES-I-100	ND							
2nd Floor C203	Sink	8/26/2016	NHES-I-101	ND							
2nd Floor C204	Fountain	8/26/2016	NHES-I-102	ND							
2nd Floor C204	Sink	8/26/2016	NHES-I-103	ND							
2nd Floor Girls Restroom 213 (left)	Sink	8/26/2016	NHES-I-104	2.82							
2nd Floor Girls Restroom 213 (right)	Sink	8/26/2016	NHES-I-105	3.28							
2nd Floor Boys Restroom 212 (left)	Sink	8/26/2016	NHES-I-106	2.21							
2nd Floor Boys Restroom 212 (right)	Sink	8/26/2016	NHES-I-107	2.21							
2nd Floor Wheelchair Access All Gender by Room 214	Sink	8/26/2016	NHES-I-108	ND							
2nd Floor Staff Restroom by Room 214	Sink	8/26/2016	NHES-I-109	ND							
2nd Floor B201	Fountain	8/26/2016	NHES-I-110	ND							
2nd Floor B201	Sink	8/26/2016	NHES-I-111	ND							
2nd Floor B205	Fountain	8/26/2016	NHES-I-112	ND							
2nd Floor B205	Sink	8/26/2016	NHES-I-113	ND							
2nd Floor B202	Fountain	8/26/2016	NHES-I-114	ND							
2nd Floor B202	Sink	8/26/2016	NHES-I-115	ND							
2nd Floor B203	Fountain	8/26/2016	NHES-I-116	ND							
2nd Floor B203	Sink	8/26/2016	NHES-I-117	ND							
2nd Floor B204	Fountain	8/26/2016	NHES-I-118	ND							
2nd Floor B204	Sink	8/26/2016	NHES-I-119	ND							
Girls Restroom 146 (left)	Sink	8/26/2016	NHES-I-120	2.05							
Girls Restroom 146 (right)	Sink	8/26/2016	NHES-I-121	2.09							
Boys Restroom 145 (left)	Sink	8/26/2016	NHES-I-122	1.06							
Boys Restroom 145 (right)	Sink	8/26/2016	NHES-I-123	2.20							
Family Restroom by Room 143	Sink	8/26/2016	NHES-I-124	ND							
North end of Gym by Room 151 (Upper left)	Fountain	8/26/2016	NHES-I-125	ND							
North end of Gym by Room 151 (Lower right)	Fountain	8/26/2016	NHES-I-126	ND							
North end of Gym by Room 151 Elkay Unit	Bottle Filler	8/26/2016	NHES-I-127	ND							
Boom 153	Fountain	8/26/2016	NHES-I-128	1.29							
Room 153	Sink	8/26/2016	NHES-I-129	ND							
Kitchen Dishwash Sink South Wall	Sprayer	8/26/2016	NHES-I-130	1.25							
Kitchen Double Basin on Island	Sprayer	8/26/2016	NHES-I-131	ND							
Restroom Northwest of A101	Sink	8/26/2016	NHES-I-132	ND							
C102	Fountain	8/26/2016	NHES-I-133	ND							
C102	Sink	8/26/2016	NHES-I-134	ND							
Staff Room 106 Refrigerator - In Door (South right)	Ice Machine	10/8/2016	NHES-I-135	ND							
Staff Room 106 Refrigerator - In Door (North left)	Ice Machine	10/8/2016	NHES-I-136	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.