

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Madison Middle School</b>											
Boys Locker Room (Left)	Sink	6/22/2016	MADMS-I-001	1.64							
Boys Locker Room (Middle)	Sink	6/22/2016	MADMS-I-002	0.31							
Boys Locker Room (Right)	Sink	6/22/2016	MADMS-I-003	0.66							
Hallway Outside Boys Locker Room (left)	Fountain	6/22/2016	MADMS-I-004	0.60							
Hallway Outside Boys Locker Room (right)	Fountain	6/22/2016	MADMS-I-005	0.76							
Girls Locker Room (Left)	Sink	6/22/2016	MADMS-I-006	4.31							
Girls Locker Room (Middle)	Sink	6/22/2016	MADMS-I-007	1.08							
Girls Locker Room (Right)	Sink	6/22/2016	MADMS-I-008	1.39							
Kitchen Hand Wash West Wall	Sink	6/22/2016	MADMS-I-009	1.51							
Kitchen Dish Sprayer in Food Prep Area	Sink	6/22/2016	MADMS-I-010	0.58							
Kitchen Faucet in Food Prep Area	Sink	6/22/2016	MADMS-I-011	0.29							
Kitchen Hand Wash North Wall	Sink	6/22/2016	MADMS-I-012	0.32							
Kitchen Office Restroom	Sink	6/22/2016	MADMS-I-013	1.87							
Kitchen Dishwash Area Sprayer	Sink	6/22/2016	MADMS-I-014	2.27							
Kitchen Dishwash Area Faucet	Sink	6/22/2016	MADMS-I-015	0.42							
Cafeteria	Fountain	6/22/2016	MADMS-I-016	0.30							
Band Room	Sink	6/22/2016	MADMS-I-017	1.11							
Band Room	Fountain	6/22/2016	MADMS-I-018	ND							
Wheelchair Access Restroom Outside Band Room	Sink	6/22/2016	MADMS-I-019	2.47							
Boys Restroom outside Band Room (Left)	Sink	6/22/2016	MADMS-I-020	1.03							
Boys Restroom outside Band Room (Right)	Sink	6/22/2016	MADMS-I-021	0.30							
Girls Restroom outside Band Room (Left)	Sink	6/22/2016	MADMS-I-022	0.62							
Girls Restroom outside Band Room (Right)	Sink	6/22/2016	MADMS-I-023	0.39							
Room 401 (Low)	Fountain	6/22/2016	MADMS-I-024	1.67							
Room 401 (Low)	Sink	6/22/2016	MADMS-I-025	0.67							
Room 401 East Wall	Sink	6/22/2016	MADMS-I-026	2.57							
Staff only Women's Restroom	Sink	6/22/2016	MADMS-I-027	0.86							
Staff only Men's Restroom	Sink	6/22/2016	MADMS-I-028	0.50							
Room 501	Fountain	6/22/2016	MADMS-I-029	1.00							
Room 501	Sink	6/22/2016	MADMS-I-030	0.71							
Room 502	Fountain	6/22/2016	MADMS-I-031	0.82							
Room 502	Sink	6/22/2016	MADMS-I-032	0.40							
Room 503	Fountain	6/22/2016	MADMS-I-033	0.37							
Room 503	Sink	6/22/2016	MADMS-I-034	0.52							
Room 504	Fountain	6/22/2016	MADMS-I-035	1.01							
Room 504	Sink	6/22/2016	MADMS-I-036	1.20							
East Hallway by Rooms 501-505	Fountain	6/22/2016	MADMS-I-037	0.24							
Room 402 on Island	Sink	6/22/2016	MADMS-I-038	1.21							
Room 402 South Wall Station 7 (Left)	Sink	6/22/2016	MADMS-I-039	1.79							
Room 402 South Wall Station 6 (Middle)	Sink	6/22/2016	MADMS-I-040	1.32							
Room 402 South Wall Station 5 (Right)	Sink	6/22/2016	MADMS-I-041	0.96							
Room 402 West Wall Station 4	Sink	6/22/2016	MADMS-I-042	0.64							
Room 402 North Wall Station 3 (Left)	Sink	6/22/2016	MADMS-I-043	0.69							
Room 402 North Wall Station 2 (Middle)	Sink	6/22/2016	MADMS-I-044	0.67							
Room 402 North Wall Station 1 (Right)	Sink	6/22/2016	MADMS-I-045	0.65							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Madison Middle School</b>											
Room 403	Fountain	6/22/2016	MADMS-I-046	0.64							
Room 403	Sink	6/22/2016	MADMS-I-047	ND							
Room 404	Sink	6/22/2016	MADMS-I-048	ND							
Room 404	Fountain	6/22/2016	MADMS-I-049	0.46							
Outside Room 609	Fountain	6/22/2016	MADMS-I-050	0.37							
Room 405	Fountain	6/22/2016	MADMS-I-051	0.47							
Room 405	Sink	6/22/2016	MADMS-I-052	ND							
Boys Restroom (Left)	Sink	6/22/2016	MADMS-I-053	0.69							
Boys Restroom (Right)	Sink	6/22/2016	MADMS-I-054	0.22							
Girls Restroom (Left)	Sink	6/22/2016	MADMS-I-055	1.02							
Girls Restroom (Right)	Sink	6/22/2016	MADMS-I-056	0.31							
Room 604	Fountain	6/22/2016	MADMS-I-057	0.57							
Room 604	Sink	6/22/2016	MADMS-I-058	0.40							
Room 603 Island	Sink	6/22/2016	MADMS-I-059	10.50							
Room 603	Fountain	6/22/2016	MADMS-I-060	1.24							
Room 603 East Wall (Left)	Sink	6/22/2016	MADMS-I-061	3.20							
Room 603 East Wall (Middle)	Sink	6/22/2016	MADMS-I-062	7.50							
Room 603 East Wall (Right)	Sink	6/22/2016	MADMS-I-063	2.02							
Room 603 West Wall (Left)	Sink	6/22/2016	MADMS-I-064	7.51							
Room 603 West Wall (Middle)	Sink	6/22/2016	MADMS-I-065	5.75							
Room 603 West Wall (Right)	Sink	6/22/2016	MADMS-I-066	3.28							
Room 602 Island	Sink	6/22/2016	MADMS-I-067	18.10							
Room 602 South Wall	Fountain	6/22/2016	MADMS-I-068	1.75							
Room 602 South Wall (Right)	Sink	6/22/2016	MADMS-I-069	3.56							
Room 602 South Wall (Middle)	Sink	6/22/2016	MADMS-I-070	2.87							
Room 602 North Wall (Left)	Sink	6/22/2016	MADMS-I-071	4.79							
Room 602 North Wall (Middle)	Sink	6/22/2016	MADMS-I-072	4.37							
Room 602 North Wall (Middle)	Sink	6/22/2016	MADMS-I-073	6.41							
Room 602 North Wall (Left)	Sink	6/22/2016	MADMS-I-074	2.08							
Room 610	Sink	6/22/2016	MADMS-I-075	3.86							
Room 610 South Wall (Left)	Fountain	6/22/2016	MADMS-I-076	1.82							
Room 601 South Wall (Left)	Sink	6/22/2016	MADMS-I-077	2.73							
Room 601 South Wall (Middle)	Sink	6/22/2016	MADMS-I-078	5.77							
Room 601 South Wall (Right)	Sink	6/22/2016	MADMS-I-079	5.40							
Room 601 Island	Sink	6/22/2016	MADMS-I-080	9.61							
Room 601 North Wall (Left)	Sink	6/22/2016	MADMS-I-081	1.74							
Room 601 North Wall (Middle)	Sink	6/22/2016	MADMS-I-082	1.89							
Room 601 North Wall (Right)	Sink	6/22/2016	MADMS-I-083	6.32							
Boys Restroom Across From Room 402 (Left)	Sink	6/22/2016	MADMS-I-084	1.03							
Boys Restroom Across from Room 402 (Right)	Sink	6/22/2016	MADMS-I-085	0.49							
Girls Restroom across from Room 402 (Left)	Sink	6/22/2016	MADMS-I-086	1.10							
Girls Restroom across from Room 402 (Right)	Sink	6/22/2016	MADMS-I-087	0.47							
2nd Floor Girls Wheelchair Access Restroom by Elevator	Sink	6/22/2016	MADMS-I-088	1.72							
2nd Floor Boys Wheelchair Access Restroom by Elevator	Sink	6/22/2016	MADMS-I-089	1.07							
2nd Floor Next to Wheelchair Access Restroom	Fountain	6/22/2016	MADMS-I-090	0.21							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Madison Middle School</b>											
2nd Floor Workroom in Media Center 704	Sink	6/22/2016	MADMS-I-091	0.48							
2nd Floor Workroom in Media Center 704	Insta-Hot	6/22/2016	MADMS-I-092	0.34							
2nd Floor Room 705	Fountain	6/22/2016	MADMS-I-093	0.68							
2nd Floor Room 705 South Wall Right Side	Sink	6/22/2016	MADMS-I-094	0.33							
2nd Floor Room 705 South Wall Left Side	Sink	6/22/2016	MADMS-I-095	0.87							
2nd Floor Room 705 South Wall Long Sink	Sink	6/22/2016	MADMS-I-096	0.53							
2nd Floor Outside Block 9-4	Fountain	6/22/2016	MADMS-I-097	ND							
2nd Floor Block 904	Fountain	6/22/2016	MADMS-I-098	1.28							
2nd Floor Block 904	Sink	6/22/2016	MADMS-I-099	0.74							
2nd Floor Block 903	Fountain	6/22/2016	MADMS-I-100	0.22							
2nd Floor Block 903	Sink	6/22/2016	MADMS-I-101	0.47							
2nd Floor Block 902	Fountain	6/22/2016	MADMS-I-102	ND							
2nd Floor Block 902	Sink	6/22/2016	MADMS-I-103	0.58							
2nd Floor Block 901	Fountain	6/22/2016	MADMS-I-104	0.57							
2nd Floor Block 901	Sink	6/22/2016	MADMS-I-105	0.63							
2nd Floor Boys Restroom in Main Hallway (Left) South End	Sink	6/22/2016	MADMS-I-106	1.47							
2nd Floor Boys Restroom in Main Hallway (Right) South End	Sink	6/22/2016	MADMS-I-107	0.40							
2nd Floor Girls Restroom in Main Hallway (Left) South End	Sink	6/22/2016	MADMS-I-108	1.14							
2nd Floor Girls Restroom in Main Hallway (Right) South End	Sink	6/22/2016	MADMS-I-109	0.41							
2nd Floor Boys Restroom in Main Hallway (Left) North End	Sink	6/22/2016	MADMS-I-110	0.81							
2nd Floor Boys Restroom in Main Hallway (Right) North End	Sink	6/22/2016	MADMS-I-111	0.24							
2nd Floor Girls Restroom in Main Hallway (Left) North End	Sink	6/22/2016	MADMS-I-112	1.54							
2nd Floor Girls Restroom in Main Hallway (Right) North End	Sink	6/22/2016	MADMS-I-113	0.26							
2nd Floor Room 804	Fountain	6/22/2016	MADMS-I-114	0.48							
2nd Floor Room 804	Sink	6/22/2016	MADMS-I-115	0.68							
2nd Floor Room 803	Fountain	6/22/2016	MADMS-I-116	1.38							
2nd Floor Room 803	Sink	6/22/2016	MADMS-I-117	0.37							
2nd Floor Block 802	Fountain	6/22/2016	MADMS-I-118	1.00							
2nd Floor Block 802	Sink	6/22/2016	MADMS-I-119	0.50							
2nd Floor Block 801	Fountain	6/22/2016	MADMS-I-120	0.49							
2nd Floor Block 801	Sink	6/22/2016	MADMS-I-121	0.53							
1st Floor Workroom 121	Sink	6/22/2016	MADMS-I-122	1.58							
1st Floor Staff Room 122	Sink	6/22/2016	MADMS-I-123	0.47							
1st Floor Main Office Restroom Men's	Sink	6/22/2016	MADMS-I-124	0.62							
1st Floor Main Office Restroom Women's	Sink	6/22/2016	MADMS-I-125	0.43							
Room 107 - Office	Sink	9/7/2016	MADMS-I-126	ND							
Room 107 - Office	Insta-Hot	9/7/2016	MADMS-I-127	ND							
Room 108 - Health Room	Sink	9/7/2016	MADMS-I-128	1.28							
Room 108 - Restroom	Sink	9/7/2016	MADMS-I-129	1.95							
Staff Room 122 Ice Machine	Ice Machine	9/7/2016	MADMS-I-130	ND							
Pre-School Room 401 Northeast Wall Ice Machine	Ice Machine	9/7/2016	MADMS-I-131	3.89							
Consumer Studies Room 402 East Wall Ice Machine	Ice Machine	9/7/2016	MADMS-I-132	4.88							
RLC Room 403 Northwest Wall Ice Machine	Ice Machine	10/8/2016	MADMS-I-133	1.37							
Science Prep Area Between Rooms 601 & 602 East Ice Machine	Ice Machine	10/8/2016	MADMS-I-134	ND							
Room 108 Health Room Ice Machine	Ice Machine	10/8/2016	MADMS-I-135	1.97							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
 Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw			
Madison Middle School	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Ice Machine outside Boiler Room 223	Ice Machine	10/8/2016	MADMS-I-136	5.54							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.