

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location River Road/El Camino del Río Elementary School	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Cafeteria	Fountain	6/28/2016	RRES-I-001	1.04							
Kitchen Prep Sink	Sink	6/28/2016	RRES-I-002	2.10							
Kitchen Dishwasher Area	Sprayer	6/28/2016	RRES-I-003	2.08							
Kitchen Dishwasher Area	Sink	6/28/2016	RRES-I-004	0.91							
North Unisex Restroom near office	Sink	6/28/2016	RRES-I-005	2.06							
South Unisex Restroom near office	Sink	6/28/2016	RRES-I-006	0.66							
Health Room	Sink	6/28/2016	RRES-I-007	3.17							
Corridor across form Room 1B	Fountain	6/28/2016	RRES-I-008	6.92							
Room 1B	Sink	6/28/2016	RRES-I-009	8.89							
Room 2	Fountain	6/28/2016	RRES-I-010	2.73							
Room 2	Sink	6/28/2016	RRES-I-011	2.22							
Room 11	Fountain	6/28/2016	RRES-I-012	13.90							
Room 11	Sink	6/28/2016	RRES-I-013	12.20							
Room 10	Fountain	6/28/2016	RRES-I-014	6.53							
Room 10	Sink	6/28/2016	RRES-I-015	5.30							
Room 9-11 Corridor	Fountain	6/28/2016	RRES-I-016	6.34							
Room 9	Fountain	6/28/2016	RRES-I-017	11.50							
Room 9	Sink	6/28/2016	RRES-I-018	9.99							
Staff Lounge	Insta-Hot	6/28/2016	RRES-I-019	0.36							
Staff Lounge	Sink	6/28/2016	RRES-I-020	2.64							
Room 3	Fountain	6/28/2016	RRES-I-021	2.01							
Room 3	Sink	6/28/2016	RRES-I-022	4.41							
Staff Men's Restroom	Sink	6/28/2016	RRES-I-023	2.30							
Staff Women's Restroom	Sink	6/28/2016	RRES-I-024	1.57							
Central Corridor Center Boys Restroom (South)	Sink	6/28/2016	RRES-I-025	2.90							
Central Corridor Center Boys Restroom (Center)	Sink	6/28/2016	RRES-I-026	3.46							
Central Corridor Center Boys Restroom (North)	Sink	6/28/2016	RRES-I-027	2.27							
Central Corridor Center Girls Restroom (South)	Sink	6/28/2016	RRES-I-028	4.27							
Central Corridor Center Girls Restroom (Center)	Sink	6/28/2016	RRES-I-029	3.28							
Central Corridor Center Girls Restroom (North)	Sink	6/28/2016	RRES-I-030	7.91							
Central Corridor Near Room 4	Fountain	6/28/2016	RRES-I-031	17.00							
Room 4	Fountain	6/28/2016	RRES-I-032	2.36							
Room 4	Sink	6/28/2016	RRES-I-033	5.83							
Room 14	Fountain	6/28/2016	RRES-I-034	10.00							
Room 14	Sink	6/28/2016	RRES-I-035	9.17							
Room 13	Fountain	6/28/2016	RRES-I-036	2.61							
Room 13	Sink	6/28/2016	RRES-I-037	2.29							
Rooms 12-14 Corridor	Fountain	6/28/2016	RRES-I-038	2.74							
Room 12	Fountain	6/28/2016	RRES-I-039	6.43							
Room 12	Sink	6/28/2016	RRES-I-040	8.71							
Room 23	Fountain	6/28/2016	RRES-I-041	1.61							
Room 23	Sink	6/28/2016	RRES-I-042	4.24							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location River Road/El Camino del Río Elementary School	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Room 5	Fountain	6/28/2016	RRES-I-043	5.61							
Room 5	Sink	6/28/2016	RRES-I-044	20.90	8/18/2016	RRES-F-083	ND	8/24/2016	8/26/2016	RRES-I-087	9.31
Smart	Fountain	6/28/2016	RRES-I-045	35.60	8/18/2016	RRES-F-084	2.53	8/24/2016	8/26/2016	RRES-I-088	2.37
Smart	Sink	6/28/2016	RRES-I-046	35.10	8/18/2016	RRES-F-085	1.77	8/24/2016	8/26/2016	RRES-I-089	6.18
Book Storage Room	Sink	6/28/2016	RRES-I-047	6.62							
Central Corridor Near Library	Fountain	6/28/2016	RRES-I-048	6.22							
Room 6	Fountain	6/28/2016	RRES-I-049	1.54							
Room 6	Sink	6/28/2016	RRES-I-050	6.39							
EEP Room	Fountain	6/28/2016	RRES-I-051	3.48							
EEP Room	Sink	6/28/2016	RRES-I-052	3.50							
Music Room	Fountain	6/28/2016	RRES-I-053	4.44							
Music Room	Sink	6/28/2016	RRES-I-054	26.70	8/18/2016	RRES-F-082	3.44	8/24/2016	8/26/2016	RRES-I-091	11.40
Room 7	Fountain	6/28/2016	RRES-I-055	2.92							
Room 7	Sink	6/28/2016	RRES-I-056	7.54							
Central Corridor West End Boys Restroom (South)	Sink	6/28/2016	RRES-I-057	4.13							
Central Corridor West End Boys Restroom (Center)	Sink	6/28/2016	RRES-I-058	3.75							
Central Corridor West End Boys Restroom (North)	Sink	6/28/2016	RRES-I-059	4.03							
Central Corridor West End Girls Restroom (South)	Sink	6/28/2016	RRES-I-060	3.91							
Central Corridor West End Girls Restroom (Center)	Sink	6/28/2016	RRES-I-061	4.16							
Central Corridor West End Girls Restroom (North)	Sink	6/28/2016	RRES-I-062	2.84							
Central Corridor West End	Fountain	6/28/2016	RRES-I-063	4.07							
Room 8	Fountain	6/28/2016	RRES-I-064	4.58							
Room 8	Sink	6/28/2016	RRES-I-065	20.80	8/18/2016	RRES-F-086	4.47	8/24/2016	8/26/2016	RRES-I-090	2.73
Room 19	Fountain	6/28/2016	RRES-I-066	1.95							
Room 19	Sink	6/28/2016	RRES-I-067	2.55							
Room 18	Fountain	6/28/2016	RRES-I-068	1.54							
Room 18	Sink	6/28/2016	RRES-I-069	4.82							
Room 17	Fountain	6/28/2016	RRES-I-070	5.06							
Room 17	Sink	6/28/2016	RRES-I-071	16.40							
Rooms 24-26 Addition Boys Restroom	Sink	6/28/2016	RRES-I-072	1.82							
Rooms 24-26 Addition Girls Restroom	Sink	6/28/2016	RRES-I-073	3.72							
Rooms 24-26 Addition Corridor	Fountain	6/28/2016	RRES-I-074	1.82							
Room 26	Sink	6/28/2016	RRES-I-075	1.65							
Room 26	Fountain	6/28/2016	RRES-I-076	1.21							
Room 25	Fountain	6/28/2016	RRES-I-077	0.52							
Room 25	Sink	6/28/2016	RRES-I-078	0.61							
Room 24	Fountain	6/28/2016	RRES-I-079	0.87							
Room 24	Sink	6/28/2016	RRES-I-080	1.48							
Staff Room Refrigerator - In Freezer	Ice Machine	10/8/2016	RRES-I-092	ND							
Hallway DF between Room 2 & 3	Fountain	Removed - No longer in service									

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.