

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Roosevelt Middle School (OLD)											
Girls Locker Room Restroom	Sink	6/20/2016	RMS-I-001	6.60	6/20/2016	RMS-I-002					
Custodial Office	Sink	6/20/2016	RMS-I-003	3.38	6/20/2016	RMS-I-004					
Kitchen Handwashing Sink	Sink	6/20/2016	RMS-I-005	2.67	6/20/2016	RMS-I-006					
Kitchen Produce Sink	Sink	6/20/2016	RMS-I-007	ND	6/20/2016	RMS-I-008					
Kitchen Dishwashing Sink	Sink	6/20/2016	RMS-I-009	17.80	6/20/2016	RMS-I-010					
Boys Gym	Fountain	6/20/2016	RMS-I-011	3.75	6/20/2016	RMS-I-012					
Cafeteria Corridor	Fountain	6/20/2016	RMS-I-013	8.18	6/20/2016	RMS-I-014					
Room B12, West	Sink	6/20/2016	RMS-I-015	119.00	6/20/2016	RMS-I-016	2.89				
Room B12, East	Sink	6/20/2016	RMS-I-017	20.90	6/20/2016	RMS-I-018	3.48				
Room B13	Sink	6/20/2016	RMS-I-019	18.70	6/20/2016	RMS-I-020					
Room B11	Sink	6/20/2016	RMS-I-021	183.00	6/20/2016	RMS-I-022	2.63				
Room B10	Sink	6/20/2016	RMS-I-023	14.70	6/20/2016	RMS-I-024					
Room B9 Station 5	Sink	6/20/2016	RMS-I-025	12.10	6/20/2016	RMS-I-026					
Room B9 Station 6	Sink	6/20/2016	RMS-I-027	6.37	6/20/2016	RMS-I-028					
Room B9 Station 7	Sink	6/20/2016	RMS-I-029	6.25	6/20/2016	RMS-I-030					
Room B9 Station 1	Sink	6/20/2016	RMS-I-031	7.54	6/20/2016	RMS-I-032					
Room B9 Station 2	Sink	6/20/2016	RMS-I-033	2.56	6/20/2016	RMS-I-034					
Room B9 Station 3	Sink	6/20/2016	RMS-I-035	3.25	6/20/2016	RMS-I-036					
Room B9 Station 4	Sink	6/20/2016	RMS-I-037	2.90	6/20/2016	RMS-I-038					
Room B7 Office	Sink	6/20/2016	RMS-I-039	9.17	6/20/2016	RMS-I-040					
Room B6 Office	Sink	6/20/2016	RMS-I-041	11.10	6/20/2016	RMS-I-042					
Main B Hall Corridor	Fountain	6/20/2016	RMS-I-043	1.45	6/20/2016	RMS-I-044					
B Hall Girls Restroom (East)	Sink	6/20/2016	RMS-I-045	1.28	6/20/2016	RMS-I-046					
B Hall Girls Restroom (West)	Sink	6/20/2016	RMS-I-047	1.34	6/20/2016	RMS-I-048					
Room B5 Office	Sink	6/20/2016	RMS-I-049	19.30	6/20/2016	RMS-I-050					
Room B3 Office	Sink	6/20/2016	RMS-I-051	67.40	6/20/2016	RMS-I-052	5.01				
Room B3A	Sink	6/20/2016	RMS-I-053	5.74	6/20/2016	RMS-I-054					
Main B Hall Corridor North End	Fountain	6/20/2016	RMS-I-055	2.97	6/20/2016	RMS-I-056					
Room A4, SW Corner	Sink	6/20/2016	RMS-I-057	108.00	6/20/2016	RMS-I-058	23.60				
Room A4, West	Sink	6/20/2016	RMS-I-059	39.20	6/20/2016	RMS-I-060	13.50				
Room A4 Northwest Sink	Sink	6/20/2016	RMS-I-061	11.20	6/20/2016	RMS-I-062					
Room A4 Northeast Sink	Sink	6/20/2016	RMS-I-063	4.78	6/20/2016	RMS-I-064					
Room A4, East	Sink	6/20/2016	RMS-I-065	97.70	6/20/2016	RMS-I-066	2.42				
Room A4, Demonstration Table	Sink	6/20/2016	RMS-I-067	58.40	6/20/2016	RMS-I-068	2.98				
Room A3 South Counter West Sink	Sink	6/20/2016	RMS-I-069	6.95	6/20/2016	RMS-I-070					
Room A3 South Counter East Sink	Sink	6/20/2016	RMS-I-071	4.78	6/20/2016	RMS-I-072					
Room A3, East	Sink	6/20/2016	RMS-I-073	47.10	6/20/2016	RMS-I-074	1.61				
Room A3 West Counter North Side	Sink	6/20/2016	RMS-I-075	4.06	6/20/2016	RMS-I-076					
Room A3 West Counter South Side	Sink	6/20/2016	RMS-I-077	9.63	6/20/2016	RMS-I-078					
Room A4 West Counter South Side	Sink	6/20/2016	RMS-I-079	4.25	6/20/2016	RMS-I-080					
Room A2, West Counter-North	Sink	6/20/2016	RMS-I-081	21.20	6/20/2016	RMS-I-082	2.10				
Room A4 North Counter West Side	Sink	6/20/2016	RMS-I-083	6.61	6/20/2016	RMS-I-084					
Room A4 North Counter East Side	Sink	6/20/2016	RMS-I-085	2.88	6/20/2016	RMS-I-086					

Flushed July 2016

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Roosevelt Middle School (OLD)											
Room A1, East Counter-North	Sink	6/20/2016	RMS-I-087	29.00	6/20/2016	RMS-I-088	6.93				
Room A1, East Counter-South	Sink	6/20/2016	RMS-I-089	45.20	6/20/2016	RMS-I-090	4.08				
Library Work Room	Sink	6/20/2016	RMS-I-091	3.33	6/20/2016	RMS-I-092					
Boiler Room	Sink	6/20/2016	RMS-I-093	12.00	6/20/2016	RMS-I-094					
E Hall Corridor	Fountain	6/20/2016	RMS-I-095	8.65	6/20/2016	RMS-I-096					
Room E3, Back Stage Counter	Sink	6/20/2016	RMS-I-097	870.00	6/20/2016	RMS-I-098	32.10				
Staff Mail Room	Sink	6/20/2016	RMS-I-099	6.12	6/20/2016	RMS-I-100					
Central Corridor Upper Fountain	Fountain	6/20/2016	RMS-I-101	5.20	6/20/2016	RMS-I-102					
Central Corridor Lower Fountain	Fountain	6/20/2016	RMS-I-103	3.45	6/20/2016	RMS-I-104					
Staff Lounge	Sink	6/20/2016	RMS-I-105	4.16	6/20/2016	RMS-I-106					
Staff Lounge	Insta-Hot	6/20/2016	RMS-I-107	0.43	6/20/2016	RMS-I-108					
Central Corridor Boys Restroom (North)	Sink	6/20/2016	RMS-I-109	1.96	6/20/2016	RMS-I-110					
Central Corridor Boys Restroom (South)	Sink	6/20/2016	RMS-I-111	0.92	6/20/2016	RMS-I-112					
Central Corridor Girls Restroom (South)	Sink	6/20/2016	RMS-I-113	1.28	6/20/2016	RMS-I-114					
Central Corridor Girls Restroom (North)	Sink	6/20/2016	RMS-I-115	0.69	6/20/2016	RMS-I-116					
Room C3	Sink	6/20/2016	RMS-I-117	18.70	6/20/2016	RMS-I-118					
Room C3	Fountain	6/20/2016	RMS-I-119	2.05	6/20/2016	RMS-I-120					
Room C4	Sink	6/20/2016	RMS-I-121	8.76	6/20/2016	RMS-I-122					
Room C4	Fountain	6/20/2016	RMS-I-123	1.91	6/20/2016	RMS-I-124					
Room C5	Sink	6/20/2016	RMS-I-125	9.49	6/20/2016	RMS-I-126					
Room C5	Fountain	6/20/2016	RMS-I-127	1.00	6/20/2016	RMS-I-128					
Room C6	Sink	6/20/2016	RMS-I-129	18.10	6/20/2016	RMS-I-130					
Room C6	Fountain	6/20/2016	RMS-I-131	3.39	6/20/2016	RMS-I-132					
D Hall Corridor (South)	Fountain	6/20/2016	RMS-I-133	4.75	6/20/2016	RMS-I-134					
D Hall Corridor (North)	Fountain	6/20/2016	RMS-I-135	5.48	6/20/2016	RMS-I-136					
Band Entry Vestibule	Fountain	6/20/2016	RMS-I-137	11.20	6/20/2016	RMS-I-138					
Room D3 Office	Sink	6/20/2016	RMS-I-139	134.00	6/20/2016	RMS-I-140	3.51				
Room D5 Office	Sink	6/20/2016	RMS-I-141	256.00	6/20/2016	RMS-I-142	3.47				
Room D4 Office	Sink	6/20/2016	RMS-I-143	55.30	6/20/2016	RMS-I-144	8.63				
Room D7	Sink	6/20/2016	RMS-I-145	17.90	6/20/2016	RMS-I-146					
Room D6 Office	Sink	6/20/2016	RMS-I-147	37.50	6/20/2016	RMS-I-148	3.14				
D Hall Girls Restroom (West)	Sink	6/20/2016	RMS-I-149	3.45	6/20/2016	RMS-I-150					
D Hall Girls Restroom (East)	Sink	6/20/2016	RMS-I-151	5.68	6/20/2016	RMS-I-152					
D Hall Boys Restroom, East	Sink	6/20/2016	RMS-I-153	31.90	6/20/2016	RMS-I-154	0.79				
D Hall Boys Restroom (West)	Sink	6/20/2016	RMS-I-155	8.31	6/20/2016	RMS-I-156					
Room D12, South	Sink	6/20/2016	RMS-I-157	30.20	6/20/2016	RMS-I-158	1.65				
Room D12, North	Sink	6/20/2016	RMS-I-159	119.00	6/20/2016	RMS-I-160	1.52				
Room D12	Fountain	6/20/2016	RMS-I-161	7.17	6/20/2016	RMS-I-162					

Building Demo

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.