

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw					
Corridor Elementary School/Yujin Gakuen Japanese Immersion Elementary School		Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Flushed	Date Sampled	Sample ID #	Result (ppb)
Staff Room	Sink	6/28/16	YGES-I-001	0.38													
Nurse's Room	Sink	6/28/16	YGES-I-002	0.88													
Employee Restroom in Office (L)	Sink	6/28/16	YGES-I-003	4.71													
Employee Restroom in Office (L)	Sink	6/28/16	YGES-I-004	1.98													
IMC	Sink	6/28/16	YGES-I-005	4.51													
IMC	Insta-Hot	6/28/16	YGES-I-006	1.31													
Library	Fountain	6/28/16	YGES-I-007	4.88													
Room 7A	Sink	6/28/16	YGES-I-008	1.30													
Girls Restroom Across from Room 7A (L)	Sink	6/28/16	YGES-I-009	2.10													
Girls Restroom Across from Room 7A (R)	Sink	6/28/16	YGES-I-010	1.53													
Boys Restroom Across from Room 7A (L)	Sink	6/28/16	YGES-I-011	2.84													
Boys Restroom Across from Room 7A (R)	Sink	6/28/16	YGES-I-012	2.41													
Room 7	Fountain	6/28/16	YGES-I-013	1.71													
Room 7	Sink	6/28/16	YGES-I-014	1.37													
Room 1	Fountain	6/28/16	YGES-I-015	2.98													
Room 1	Sink	6/28/16	YGES-I-016	1.87													
Room 6	Fountain	6/28/16	YGES-I-017	0.94													
Room 6	Sink	6/28/16	YGES-I-018	1.32													
Room 2	Fountain	6/28/16	YGES-I-019	2.31													
Room 2	Sink	6/28/16	YGES-I-020	2.94													
Room 5	Fountain	6/28/16	YGES-I-021	1.59													
Room 5	Sink	6/28/16	YGES-I-022	1.83													
Room 3	Fountain	6/28/16	YGES-I-023	1.67													
Room 3	Sink	6/28/16	YGES-I-024	1.52													
Room 4	Fountain	6/28/16	YGES-I-025	1.99													
Room 4	Sink	6/28/16	YGES-I-026	1.61													
Room 20 (Labeled 12 on bldg)	Fountain	6/28/16	YGES-I-027	3.53													
Room 20 (Labeled 12 on bldg)	Sink	6/28/16	YGES-I-028	1.80													
Room 19 (Labeled 11 on bldg)	Fountain	6/28/16	YGES-I-029	7.76													
Room 19 (Labeled 11 on bldg)	Sink	6/28/16	YGES-I-030	3.60													
Room 22 (Labeled 13 on bldg)	Fountain	6/28/16	YGES-I-031	1.61													
Room 22 (Labeled 13 on bldg)	Sink	6/28/16	YGES-I-032	2.54													
Room 21 (Labeled 14 on bldg)	Fountain	6/28/16	YGES-I-033	2.37													
Room 21 (Labeled 14 on bldg)	Sink	6/28/16	YGES-I-034	2.78													
Girls Restroom in Breezeway (L)	Sink	6/28/16	YGES-I-035	1.57													
Girls Restroom in Breezeway (R)	Sink	6/28/16	YGES-I-036	1.37													
Breezeway Between Restrooms	Fountain	6/28/16	YGES-I-037	47.00	8/16/16	YGES-F-079	12.70	9/1/16	9/2/16	YGES-I-083	52.80	1. Removed section of feeder pipe and multiple fitting. Re-plumbed with lead free components. 2. Re-fed DF from different location.	1. 10/11/2016 2. 7/12/2017	1. 10/12/2016 2. 7/13/2017	1. YGES-I-085 2. YGES-I-088	1. 42.70 2. ND	
Boys Restroom in Breezeway (L)	Sink	6/28/16	YGES-I-038	7.51													
Boys Restroom in Breezeway (R)	Sink	6/28/16	YGES-I-039	8.42													
Shop	Fountain	6/28/16	YGES-I-040	13.00													
Shop	Sink	6/28/16	YGES-I-041	6.10													
Room 8	Fountain	6/28/16	YGES-I-042	1.57													
Room 9	Sink	6/28/16	YGES-I-043	0.93													
Room 10	Sink	6/28/16	YGES-I-044	1.61													
Office	Sink	6/28/16	YGES-I-045	2.03													
Girls Restroom Across from Room 10 (L)	Sink	6/28/16	YGES-I-046	1.10													
Girls Restroom Across from Room 10 (R)	Sink	6/28/16	YGES-I-047	1.31													
Room 18	Fountain	6/28/16	YGES-I-048	ND													
Room 18	Sink	6/28/16	YGES-I-049	0.47													
Restroom Across from Room 17	Sink	6/28/16	YGES-I-050	0.29													
Boys Restroom Across from Room 17 (L)	Sink	6/28/16	YGES-I-051	1.42													
Boys Restroom Across from Room 17 (R)	Sink	6/28/16	YGES-I-052	1.63													
Room 17	Fountain	6/28/16	YGES-I-053	0.88													
Room 17	Sink	6/28/16	YGES-I-054	1.16													
Room 16	Fountain	6/28/16	YGES-I-055	ND													
Room 16	Sink	6/28/16	YGES-I-056	2.88													
Room 11	Fountain	6/28/16	YGES-I-057	0.25													
Room 11	Sink	6/28/16	YGES-I-058	4.41													
Room 12	Fountain	6/28/16	YGES-I-059	0.60													
Room 12	Sink	6/28/16	YGES-I-060	2.17													
Staff Lounge Between Rooms 12 & 13	Sink	6/28/16	YGES-I-061	0.67													
Room 15	Fountain	6/28/16	YGES-I-062	0.35													
Room 15	Sink	6/28/16	YGES-I-063	0.24													
Room 13	Fountain	6/28/16	YGES-I-064	0.30													
Room 13	Sink	6/28/16	YGES-I-065	0.93													
Room 14	Fountain	6/28/16	YGES-I-066	0.46													
Room 14	Sink	6/28/16	YGES-I-067	0.88													
Cafeteria	Fountain	6/28/16	YGES-I-068	1.30													
Boys Restroom By Cafeteria (L)	Sink	6/28/16	YGES-I-069	1.10													
Boys Restroom By Cafeteria (R)	Sink	6/28/16	YGES-I-070	0.83													
Girls Restroom By Cafeteria (L)	Sink	6/28/16	YGES-I-071	0.83													
Girls Restroom By Cafeteria (R)	Sink	6/28/16	YGES-I-072	0.86													
Gym	Fountain	6/28/16	YGES-I-073	2.18													
Kitchen - North Wall	Sink	6/28/16	YGES-I-074	0.28													
Kitchen - East Wall	Sink	6/28/16	YGES-I-075	0.92													
Kitchen - Ladies Restroom	Sink	6/28/16	YGES-I-076	21.10	8/16/16	YGES-F-078	1.78	9/1/16	9/2/16	YGES-I-084	2.74						
Dishwasher Sprayer in Kitchen	Sink	6/28/16	YGES-I-077	ND													
Missed - Hallway rm 7-7A	Fountain	8/16/16	YGES-I-080	ND													
Missed - Room 8 south wall	Sink	8/16/16	YGES-I-081	2.49													

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
 Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
Missed - Room 9 south wall	Fountain	8/16/16	YGES-I-082	ND											
YG Staff Room Refrigerator - In Door	Ice Machine	10/12/16	YGES-I-086	ND											
YG Staff Room Refrigerator - In Door	Dispencer	10/12/16	YGES-I-087	ND											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.