

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw					
Twin Oaks Elementary School		Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Flushed	Date Sampled	Sample ID #	Result (ppb)
Health Room	Sink	7/11/16	TOES-001	3.54													
Health Room Restroom	Sink	7/11/16	TOES-002	5.32													
Staff Lounge	Insta-Hot	7/11/16	TOES-003	0.74													
Staff Lounge	Sink	7/11/16	TOES-004	0.96													
Principal Office	Sink	7/11/16	TOES-005	43.90	9/1/16	TOES-051	1.56	9/6/16	10/13/16	TOES-1056	80.08	Replaced Angle Stops & nipples Replaced drop ear 90's in wall	1. 2/9/2017 2. 7/13/2017	1. 2/10/2017 2. 7/14/2017	1. TOES-1059 2. TOES-1060	1. 28.10 2. 14.70	
Girls Restroom near Conference Room	Sink	7/11/16	TOES-006	1.91													
Boys Restroom near Conference Room	Sink	7/11/16	TOES-007	1.40													
Kitchen Dishwasher Area	Sprayer	7/11/16	TOES-008	2.64													
Kitchen Produce Sink	Sink	7/11/16	TOES-009	1.96													
Kitchen Handwash Sink	Sink	7/11/16	TOES-010	1.74													
Kitchen Restroom	Sink	7/11/16	TOES-011	5.96													
Cafeteria	Fountain	7/11/16	TOES-012	0.85													
Instructional Materials Center	Sink	7/11/16	TOES-013	4.90													
Room 11	Sink	7/11/16	TOES-014	2.55													
Boys Lower Level Restroom (East)	Sink	7/11/16	TOES-015	1.50													
Boys Lower Level Restroom (West)	Sink	7/11/16	TOES-016	1.80													
Girls Lower Level Restroom (East)	Sink	7/11/16	TOES-017	1.37													
Girls Lower Level Restroom (West)	Sink	7/11/16	TOES-018	1.23													
Room 12	Fountain	7/11/16	TOES-019	2.95													
Room 12	Sink	7/11/16	TOES-020	3.54													
Lower Level Storage Room	Fountain	7/11/16	TOES-021	2.66													
Lower Level Storage Room	Sink	7/11/16	TOES-022	3.03													
Classroom Wing - West End	Fountain	7/11/16	TOES-023	3.69													
Room 9	Fountain	7/11/16	TOES-024	2.14													
Room 9	Sink	7/11/16	TOES-025	3.27													
Room 10	Fountain	7/11/16	TOES-026	1.53													
Room 10	Sink	7/11/16	TOES-027	2.42													
Room 10 West Restroom	Sink	7/11/16	TOES-028	2.59													
Room 10 East Restroom	Sink	7/11/16	TOES-029	2.37													
Room 8	Sink	7/11/16	TOES-030	4.74													
Room 8	Fountain	7/11/16	TOES-031	4.62													
Room 8 West Restroom	Sink	7/11/16	TOES-032	1.71													
Room 8 East Restroom	Sink	7/11/16	TOES-033	4.13													
Room 7	Sink	7/11/16	TOES-034	3.27													
Room 7	Fountain	7/11/16	TOES-035	3.43													
Room 6	Sink	7/11/16	TOES-036	7.11													
Room 6	Fountain	7/11/16	TOES-037	3.01													
Room 6 West Restroom	Sink	7/11/16	TOES-038	14.60													
Room 6 East Restroom	Sink	7/11/16	TOES-039	3.01													
Room 5	Sink	7/11/16	TOES-040	4.92													
Room 5	Fountain	7/11/16	TOES-041	2.90													
Room 4	Sink	7/11/16	TOES-042	6.79													
Room 4	Fountain	7/11/16	TOES-043	7.20													
Room 3	Sink	7/11/16	TOES-044	5.87													
Room 3	Fountain	7/11/16	TOES-045	2.99													
Room 2	Fountain	7/11/16	TOES-046	2.24													
Room 2	Sink	7/11/16	TOES-047	3.39													
Room 1	Sink	7/11/16	TOES-048	14.10													
Room 1	Fountain	7/11/16	TOES-049	4.44													
Corridor Near Staff Lounge	Fountain	7/11/16	TOES-050	1.57													
Lower Hallway Outside Room 12	Fountain	9/1/16	TOES-052	ND													
Staff Restroom	Sink	9/1/16	TOES-053	2.84	10/13/16	TOES-055	ND	11/28/17	7/10/17	TOES-058	3.89						
Room 4 Restroom West	Sink	9/30/16	TOES-054	24.40													
Room 4 Restroom East	Sink	9/30/16	TOES-055	1.63													