

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location River Road/El Camino del Rio Elementary School (NEW)	Fixture Type	First Draw					Flushed Draw			New Fixture First Draw			
		Date Flushed	Date Sampled	Date Received	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Room A112	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-001	1.18							
Room A112	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-002	ND							
Room A110	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-003	ND							
Room A110	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-004	ND							
Room A106	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-005	ND							
Room A106	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-006	ND							
Room A104	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-007	ND							
Room A104	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-008	ND							
Room A100	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-009	ND							
Room A100	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-010	ND							
Room 117	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-011	ND							
Room 108	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-012	ND							
Room 109	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-013	ND							
Restroom 111	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-014	ND							
Restroom 110	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-015	ND							
Restroom 114	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-016	ND							
Room 104	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-017	ND							
East Restrooms, Level 1, North	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-018	ND							
East Restrooms, Level 1, Middle	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-019	1.12							
East Restrooms, Level 1, South	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-020	ND							
East Restroom, Level 1, Single Occupancy	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-021	ND							
Room A101	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-022	ND							
Room A101	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-023	ND							
Room A103	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-024	ND							
Room A103	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-025	ND							
Room A105	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-026	1.31							
Room A105	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-027	ND							
Room A107	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-028	ND							
Room A107	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-029	ND							
Room A109	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-030	ND							
Room A109	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-031	ND							
Room A111	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-032	1.06							
Room A111	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-033	2.74							
West Restroom, Level 1, Single Occupancy	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-034	ND							
West Restrooms, Level 1, South	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-035	ND							
West Restrooms, Level 1, Middle	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-036	ND							
West Restrooms, Level 1, North	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-037	ND							
West Restrooms, Level 1 - Hallway - South Upper	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-038	ND							
West Restrooms, Level 1 - Hallway - North Lower	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-039	ND							
Room A210	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-040	ND							
Room A210	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-041	ND							
Room A206	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-042	ND							
Room A206	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-043	ND							
Room A204	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-044	ND							
Room A204	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-045	ND							
Room A200	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-046	3.45							
Room A200	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-047	ND							
East Restroom, Level 2, Single Occupancy, Main Hall	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-048	ND							
East Restrooms, Level 2, North	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-049	ND							
East Restrooms, Level 2, Middle	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-050	ND							
East Restrooms, Level 2, South	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-051	ND							
East Restroom, Level 2, Single Occupancy, Adjacent RR's	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-052	ND							
Room A201	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-053	ND							
Room A201	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-054	ND							
Room A203	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-055	ND							
Room A203	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-056	ND							
Room A205	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-057	ND							
Room A205	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-058	ND							
Room A207	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-059	1.15							
Room A207	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-060	ND							
Room A209	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-061	ND							
Room A209	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-062	ND							

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw					Flushed Draw			New Fixture First Draw					
River Road/El Camino del Rio Elementary School (NEW)		Fixture Type	Date Flushed	Date Sampled	Date Received	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	
Room A211	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-063	ND									
Room A211	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-064	ND									
West Restroom, Level 2, Single Occupancy	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-065	ND									
West Restrooms, Level 2, South	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-066	ND									
West Restrooms, Level 2, Middle	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-067	ND									
West Restrooms, Level 2, North	Sink	8/5/17	8/6/17	8/18/17	ECDR-I-068	ND									
West Restrooms, Level 2 - Hallway - South Upper	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-069	ND									
West Restrooms, Level 2 - Hallway - North Lower	Fountain	8/5/17	8/6/17	8/18/17	ECDR-I-070	ND									
Stage	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-071	1.03									
Stage	Fountain	8/29/17	8/30/17	9/12/17	ECDR-I-072	ND									
Gym - Left	Fountain	8/29/17	8/30/17	9/12/17	ECDR-I-073	ND									
Gym - Right	Fountain	8/29/17	8/30/17	9/12/17	ECDR-I-074	ND									
Gym	Bottle Filler	8/29/17	8/30/17	9/12/17	ECDR-I-075	ND									
Cafeteria - Left	Fountain	8/29/17	8/30/17	9/12/17	ECDR-I-076	ND									
Cafeteria - Right	Fountain	8/29/17	8/30/17	9/12/17	ECDR-I-077	ND									
Cafeteria	Bottle Filler	8/29/17	8/30/17	9/12/17	ECDR-I-078	ND									
Cafeteria Handwash - Left	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-079	ND									
Cafeteria Handwash - Right	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-080	ND									
Gym Restroom - Single Occupancy	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-081	ND									
Gym Girls Restroom - Left	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-082	ND									
Gym Girls Restroom - Middle	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-083	ND									
Gym Girls Restroom - Right	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-084	ND									
Gym Boys Restroom - Left	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-085	ND									
Gym Boys Restroom - Middle	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-086	ND									
Gym Boys Restroom - Right	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-087	ND									
Kitchen Steam Kettle	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-088	1.91									
Kitchen Handwash @ Service Window	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-089	ND									
Kitchen West Wall Stainless Basin - Left	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-090	ND									
Kitchen West Wall Stainless Basin - Right	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-091	ND									
Kitchen West Wall Stainless Basin - Sprayer	Sprayer	8/29/17	8/30/17	9/12/17	ECDR-I-092	ND									
Kitchen South Island Handwash - Right	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-093	ND									
Kitchen South Island Stainless Basin	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-094	ND									
Kitchen South Island Stainless Basin - Sprayer	Sprayer	8/29/17	8/30/17	9/12/17	ECDR-I-095	ND									
Level 2, Restroom Area Elkay	Bottle Filler	8/29/17	8/30/17	9/12/17	ECDR-I-096	ND									
Level 1, Restroom Area Elkay	Bottle Filler	8/29/17	8/30/17	9/12/17	ECDR-I-097	ND									
Room 202	Sink	8/29/17	8/30/17	9/12/17	ECDR-I-098	ND									
Room 202	Insta-Hot	8/29/17	8/30/17	9/12/17	ECDR-I-099	ND									
Room 202 - Left Refer	Dispenser	8/29/17	8/30/17	9/12/17	ECDR-I-100	ND									
Room 202 - Right Refer	Dispenser	8/29/17	8/30/17	9/12/17	ECDR-I-101	ND									
Room 202 - Left Refer	Ice Machine	8/29/17	8/30/17	9/12/17	ECDR-I-102	ND									
Room 202 - Right Refer	Ice Machine	8/29/17	8/30/17	9/12/17	ECDR-I-103	ND									
Garden Area	Hose Bib	9/5/17	9/6/17	9/18/17	ECDR-I-104	ND									
Kitchen, Alto-Shaam Oven Washout Hose - Non-Potable	Hose	9/26/17	9/27/17	10/3/17	ECDR-I-105	23.00	Non - Potable Signage Clearly Visible from use Location								
Room 117, Refer Unit	Dispenser	9/26/17	9/27/17	10/3/17	ECDR-I-106	ND									
Room 117, Refer Unit	Ice Machine	9/26/17	9/27/17	10/3/17	ECDR-I-107	ND									
Fixture Types: DF= Drinking Fountain S= Sink IH= Instahot FR= Fridge HB= Hose Bib															
Total Samples Taken		107.00	Total Elevated on 1st Draw			107.00	Total Elevated on Flush Draw			0.00	Total Elevated on Final/Replacement Draw				0.00